SPEEDOMETER—INACCURATE SPEEDOMETER READINGS	Article No. 99-26-4

FORD: 1998-2000 EXPLORER, RANGER

MERCURY: 1998-2000 MOUNTAINEER

This TSB article is being republished in its entirety to include 2000 model year vehicles.

ISSUE

The vehicle odometer/speedometer may be inoperative or inaccurate as well as Malfunction Indicator Lamp (MIL) illuminated after the Generic Electronic Module (GEM), Central Timer Module (CTM), or the 4-Wheel Anti-lock Brake System (4WABS) Module has been replaced. This may be caused by either the GEM, CTM, or the 4WABS Module tire and axle size calibration.

ACTION

Reprogram the GEM, CTM, or 4WABS Module to match the vehicle attributes. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

In the event a 1998 through 2000 Ranger GEM/CTM/4WABS or a 1998 through 2000 Explorer/Mountaineer 4WABS/CTM component requires service or replacement, the module(s) must be configured for proper operation using a New Generation Star (NGS) Tester and version 6.0 Service function card. If you do not have version 6.0 loaded, use the latest version Service Bay Technical System (SBTS) CD to download NGS Service Function Card Version 6.0 software to the green NGS service card for configuring modules. To configure modules, follow these instructions:

1. SELECT: SERVICE BAY FUNCTIONS
2. SELECT: GEM, CTM or ABS
3. For ABS, proceed to Step 4. For GEM or CTM, SELECT: CUSTOMER PREFERENCES
4. SELECT: TIRE SIZE/AXLE RATIO CONFIGURE
   a. The NGS Tester will display "DETERMINING MODULE PROTOCOL, PLEASE WAIT"
   b. When NGS Tester is ready, press {TRIGGER} to continue.
5. ENTER TIRE SIZE/REVOLUTIONS PER MILE (REV/MILE)

NOTE
THE TIRE SIZE MUST BE ENTERED AS A REV/MILE CALCULATION. REFER TO THE REV/MILE CHART FOR THE CORRECT CALCULATION.

6. ENTER AXLE/TONE RING SIZE

NOTE
4X2 RANGERS EQUIPPED WITH A 2.5L OR 3.0L ENGINE HAVE A 7.5″ AXLE. 4X4 AND 4.0L RANGERS HAVE AN 8.8″ AXLE. ALL EXPLORERS/MOUNTAINEERS HAVE AN 8.8″ AXLE. IF THE SPECIFIC AXLE CANNOT BE SELECTED, ENTER THE AXLE TONE RING TOOTH SIZE USING (00102) FOR 7.5″ AXLES AND (00108) FOR 8.8″ AXLES.

7. ENTER OPTIONS

NOTE
SELECT 4WABS, RABS, OR NA (IF NOT EQUIPPED).

8. ENTER VEHICLE
9. SELECT: DONE - The NGS Tester will display "MODULE CONFIGURATION COMPLETE." The module is now properly configured. Press {TRIGGER} to exit.
10. Verify with road test.

REVOLUTIONS/MILE	
Tire Size	REV/Mile
P205/75R14	00800
P225/70R14	00794
P235/60R14	00797
P215/75R15	00750
P225/70R15	00761
P235/75R15	00721
P265/75R15	00679
P245/75R16	00681
P255/70R16	00690

Article No. 99-26-4 Cont'd.

OTHER APPLICABLE ARTICLES: NONE
SUPERSEDES: 99-18-13
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage And Emissions Warranty Coverage

OPERATION	DESCRIPTION	TIME
992604A	Reprogram Generic Electronic Module (GEM), Central Timer Module (CTM), Or 4-Wheel Anti-Lock Brake System (4WABS) Module	0.7 Hr.

DEALER CODING

BASIC PART NO.	CONDITION CODE
14B205	42
2C219	42

OASIS CODES: 201000, 201100, 202000, 204000, 204200, 205000, 206000, 290000, 301000, 508000