DRIVEABILITY—ROUGH IDLE AND/OR HESITATION ON ACCEL—VEHICLES BUILT BEFORE 8/26/02 EQUIPPED WITH 5.4L ENGINE AND 4R100 TRANSMISSION

Article No. 02-18-7

FORD: 2000-2003 E-350

ISSUE

Some vehicles equipped with a 5.4L Engine/4R100 transmission, federal Emissions, built before 8/26/02, may exhibit a rough idle and/or hesitation when accelerating. This may occur intermittently within the first 2-3 minutes after start when engine is not warmed up (ie. conditions other than hot restart). The condition may be aggravated by an unmetered air leak or exhaust leak. This may be caused by the Powertrain Control Module (PCM) calibration.

ACTION

Perform thorough diagnostics in accordance with the PC/ED Workshop Manual and service any unmetered air leak, exhaust leak, wiring or other related condition. Reprogram PCM with updated calibration.

SERVICE PROCEDURE

Reprogram PCM with updated calibration using WDS or NGS tester. Refer to the following PCM Calibration Chart for details.

PCM CALIBRATION INFORMATION

Application	Old Part Number (-12A650-)	Old Tear Tag	New Part Number (-12A650-)	New Tear Tag	Old Calibration	New Calibration	NGS/WDS Qualifier
2000 E-350 5.4L Fed	YC2F-PD	VNQ3	YU7Z-DUA	DMH0	0E414N0A11	0E414N0A11	WDS B20.9 Release or Later
2001 E-350 5.4L Fed	1C2F-PC	DME2	1U7Z-ERA	RHKO	1E414N0A10	1E414N0A10	WDS B20.9 Release or Later
2002 E-350 5.4L Fed	2U7A-AZA	ZLN0	2U7Z-AZB	ZLN1	2E414N0A06	2E414N0A06	WDS B20.9 Release or Later
2002 E-350 5.4L Fed	2C2A-ALB	ZGY1	2U7Z-CGA	GBC0	2E414N0A16	2E414N0A16	WDS B20.9 Release or Later
2003 E-350 5.4L Fed	3C2A-CB	KCD1	3C2Z-CC	CCN0	3E414N0A05	3E414N0A05	WDS B20.9 Release or Later

Obtain an Authorized Modifications Decal (FPS 8262 - obtainable through DOES II, 25/pkg) and list the date, dealer number, and summary of modifications performed. Select a prominent place adjacent to the Vehicle Emission Control Information Decal suitable for installing the Authorized Modifications Decal. Clean the area, install the decal, and cover it with a clear plastic decal shield.

Copyright © 2002 Ford Motor Company

AUTHORIZED MODIFICATIONS

THE FOLLOWING MODIFICATIONS HAVE BEEN MADE:
Reprogrammed Powertrain Control Module
(PCM) Per TSB 02-18-7
THESE MODIFICATIONS HAVE BEEN APPROVED, AS APPROPRIATE, BY EPA AND CARB.
DEALER NUMBER: **DATE:**
CHANGE AUTHORITY:
FPS 8262 9/78 FORD MOTOR COMPANY PRINTED IN U.S.A.

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 608000, 608400, 609000, 609400, 611000, 611500

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle.