TRACTION INVERTER MODULE (TIM) SOFTWARE UPDATE

AFFECTED VEHICLES: **CERTAIN 1998-2000 MODEL YEAR RANGER ELECTRIC VEHICLES (EV)**

OVERVIEW

SOME EV RANGER VEHICLES MAY EXHIBIT INTERMITTENT LIGHTING OF THE OIL WARNING LAMP. THIS PROCEDURE DETAILS THE PROCESS FOR UPDATING THE TIM SOFTWARE ON THE AFFECTED EV RANGER VEHICLES TO MINIMIZE THIS CONCERN.

SERVICE PROCEDURE

1. NOTE: Make sure the vehicle is NOT connected to a Power Control Station (PCS) and the climate control system and all other auxiliary loads are off when performing the following procedures. Use the standard NGS tester cable for the following procedure. Do NOT use the EEC reprogramming cable. Using the EEC reprogramming cable will cause the update to fail.

   Insert the Field Update Card into the New Generation Star (NGS) Tester.
2. Connect the NGS Tester to the data link connector (DLC) located under the steering column.
3. Wait 15 seconds.
4. Turn the ignition key to the ON (RUN) position. Do NOT go to the START position. The following screen will appear:



01B70A

5. Select UPDATE TIM SOFTWARE and press TRIGGER. The following screen will appear:



01B70B

NOTE: If the part number in the first line of this screen is YL5F-14B298-AC, do not continue. The TIM software has already been updated. Press CANCEL to abort the software update and disconnect the NGS Tester. Otherwise, continue to Step 6.

Ford Motor Company
CPR © 2001 FORD MOTOR COMPANY
DEARBORN, MICHIGAN 48121
04/01

6. NOTE: Do NOT turn the ignition key to the OFF or START position or remove the NGS data link cable while the TIM software is being updated. It is normal for instrument cluster indicators to be in a rest position and cluster lamps to illuminate during the update.


   Press TRIGGER. The following screen will appear:



01B70C

7. NOTE: **"WARNING: YOU ARE ABOUT TO OVERWRITE CURRENT SOFTWARE WITH A NEWER VERSION"** appears after pressing TRIGGER.

   Press TRIGGER. The following screen will appear:



01B70D

   Allow the update to complete (approximately 6-8 minutes). A status screen will be displayed during the update. The screen will display "UPDATE COMPLETED SUCCESSFULLY" after the update has been completed.

   If the screen displays "UPDATE FAILED" check the NGS connections and back out of the update screen using the TRIGGER button to return to the main menu. Turn ignition key to the OFF position. Disconnect the auxiliary battery negative cable. Wait two minutes, reinstall auxiliary battery negative cable and repeat steps 1 through 6.

   If the screen still displays "UPDATE FAILED", disconnect the auxiliary battery negative cable and disconnect the IAA connector for approximately two minutes. Reinstall auxiliary battery negative cable and leave the IAA connector disconnected. Repeat steps 1 through 6.

   NOTE: It may be necessary to repeat this process several times before successfully completing the download. After the update is complete, connect the IAA connector.

8. Press TRIGGER to return to main menu.
9. With the ignition switch still in the ON position, remove the Field Update Card and insert the NGS Diagnostic Card.

Ford Motor Company

CPR © 2001 FORD MOTOR COMPANY
DEARBORN, MICHIGAN 48121
04/01

10. Retrieve and clear, if necessary, continuous Diagnostic Trouble Codes (DTC) from the BCM, TIM and the IAA module.
11. Install a TIM update sticker as follows:
    a) Obtain and prepare the Authorized Modifications label. Write the modification completed, your P&A code, date of repair and the owner notification program number as shown. See Figure 1.
    b) Use isopropyl alcohol and a clean cloth to clean the lower right hand rear corner of the TIM.
    c) Wait for the alcohol to dry.
    d) Peel the backing off of the TIM update sticker and install the sticker.




FIGURE 1

Ford Motor Company
CPR © 2001 FORD MOTOR COMPANY
DEARBORN, MICHIGAN 48121
04/01