ELECTRICAL—SPEEDOMETER DROPS TO "0" MPH/KPH WHILE DRIVING—VEHICLES EQUIPPED WITH 2.5L ENGINE ONLY—VEHICLES PRODUCED BEFORE 12/31/2000	Article No. 01-18-4

FORD: 2001 RANGER

ISSUE

Some vehicles produced before 12/31/2000 equipped with 2.5L engine, may exhibit a speedometer that may drop to "0" Mph/Kph while driving. This may be caused by the Generic Electronic Module (GEM).

ACTION

Remove existing GEM (Generic Electronic Module) and replace with new GEM. Refer to the following Service Procedure for details

SERVICE PROCEDURE

Verify the speedometer drops to "0" Mph/Kph while driving.

1. Using diagnostic tool (NGS or WDS) perform inhale functions (to retrieve) vehicle parameters/attributes (i.e. tire size, axle ratio, and RABS).

NOTE

ALL 2001 RANGER TRUCKS ARE EQUIPPED WITH 4WABS, HOWEVER, THE GEM MUST BE SET TO RABS IN ORDER FOR THE GEM TO SOURCE SPEED CORRECTLY.

2. Remove existing GEM XL5Z-14B205-DB (XL5T-14B205-DE).
3. Install new GEM XL5Z-14B205-DC.
4. After new GEM has been installed, perform exhale functions from diagnostic tool to program new GEM with existing vehicle parameters/attributes.
5. Test drive to verify repair.

PART NUMBER	PART NAME
XL5Z-14B205-DC	Generic Electronic Module (GEM)

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
011804A	Replace G.E.M. (Includes Time To Verify Complaint, Retrieve Data, And Reprogram New G.E.M. Also To Verify Repair)	1.1 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
14B205	42

OASIS CODES: 204000, 204200

Copyright © 2001 Ford Motor Company