- **SEAT—DRIVER AND/OR PASSENGER SEAT TRACK "RATTLING"**
- **NOISE—"RATTLING" COMING FROM DRIVER'S AND/OR PASSENGER'S SEAT TRACK**

Article No. 02-25-5

FORD: 1998-2003 RANGER

Article **99-6-2** is being republished in its entirety to update the model year coverage.

ISSUE

Driver and/or passenger seat track may rattle (especially after a repair requiring seat removal).

ACTION

Loosen and retighten mounting bolts in proper order. This should reduce the possibility of seat track rattle. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

NOTE

THE TORQUE SEQUENCE MUST BE FOLLOWED OR THE SEAT TRACK MAY RATTLE.

1. Loosen, do not remove, all seat track mounting bolts. There are four (4) bolts per side, eight (8) bolts total (right and left side respectively).

NOTE

SUPERCAB 2- AND 4-DOOR VEHICLES CONSIST OF A SEAT TRACK KICK TRIM COVER ON THE REAR OF THE SEAT TRACK THAT WILL REQUIRE REMOVAL. THIS WILL ALLOW ACCESS TO THE REAR SEAT TRACK MOUNTING BOLT. THERE ARE A TOTAL OF FOUR (4) OF THESE COVERS, TWO (2) COVERS PER SIDE OR ONE (1) PER SEAT TRACK OUTER AND INNER SIDES. REGULAR CAB VEHICLES DO NOT HAVE THIS SEAT TRACK KICK TRIM PANEL COVER.

2. Align the seat track holes to the holes of the floorboard.
3. Retighten all bolts to 41 ± 6 Lb-ft (55 ± 8 N•m) per the following order:
   a. Front inboard
   b. Front outboard
   c. Rear inboard
   d. Rear outboard

NOTE

PERFORM THIS ORDER FOR BOTH DRIVER AND PASSENGER SIDES.

4. Verify the repair.

OTHER APPLICABLE ARTICLES: NONE
SUPERSEDES: 99-6-2
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
022505A	Repair Seat Track Rattle (Includes Time For Trim Cover Removal)	0.4 Hr.

DEALER CODING

BASIC PART NO.	CONDITION CODE
7061704	33

OASIS CODES: 101000, 702000, 702300

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle.

Copyright © 2002 Ford Motor Company