Ford Motor Company

Frank M. Ligon
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

March 2002
Revised 10/25/2002

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: DEMONSTRATION / DELIVERY HOLD: Safety Recall 02S32-Supplement #1: All 2002 Model Year Ranger vehicles with FX4 Package and a Manual Transmission—Rear Axle Replacement

REFERENCE: 1. Advance Safety Recall Notice dated January 2002 Announcing Demonstration/Delivery Hold and Safety Recall 02S32

2. DEMONSTRATION / DELIVERY HOLD: Safety Recall 02S32: All 2002 Model Year Rangers with FX4 Package and a Manual Transmission—Rear Axle Replacement

3. Dealer Announcement dated May 10, 1999, Low Volume Programs

PURPOSE OF THIS SUPPLEMENT

The original rear axle assembly used for this recall is no longer available. These parts were a direct ship from the assembly plant and are no longer in production. There were significant changes to the rear axle assembly for 2003 model year, making the rear axle assembly non transferable to the 2002 FX4 Ranger. A rear axle housing (less paint, brakes, axle shafts, vent tube, differential thrust plate and lock bolt) will now be used to complete this recall. Attachments II and III have been completely modified to accommodate this part change.

AFFECTED VEHICLES

All 2002 model year Rangers with FX4 Off-Road package and manual transmission. These vehicles were built at the Edison Assembly Plant from May 3, 2001 through January 28, 2002, and at the Twin Cities Assembly Plant from May 15, 2001 through January 09, 2002.

SAFETY CONCERN

In some of the affected vehicles, the rear axle differential may fracture under a high torque event such as when customers accelerate rapidly from a stop or where a spinning tire suddenly gains traction. A rear axle differential fracture, if not repaired, may result in rear axle lock up.

SERVICE ACTION

Before demonstrating or delivering any of the vehicles involved in this recall, the dealer must replace the rear axle housing. This must also be done on all of the affected vehicles in your inventory as well as vehicles that have been delivered to customers.

© Copyright 2002 Ford Motor Company

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to $5,000 per vehicle.

LOW VOLUME PROGRAM

This recall is being processed as a Low Volume Program. This type of field action was announced in an All-Dealer letter dated May 10, 1999.

Owners will be contacting the Low Volume Coordination Center to arrange for this service. We will advise you via CuDL (Customer Data Link) of the owners that chose your dealership to perform the service provided by this recall. The parts will be ordered for you by the Program Coordination Center.

You are requested to contact the owner and arrange for this service. (Note that our Coordination Center will advise owners that they will hear from you within the next two business days.)

ATTACHMENTS

Attachment I:	Administrative Information
Attachment II:	Labor Allowances and Parts Ordering Information
Attachment III:	Technical Information
Customer Letter	

QUESTIONS?

Claims Information:……...……...1 -800-423-8851
Other (Dealer Only) Recall Questions:……..……..……..1-800-325-5621
Low Volume Coordination Center…..……1-800-248-0186

Sincerely,

Frank M. Ligon

Frank M. Ligon
Director
Vehicle Service and Programs

© Copyright 2002 Ford Motor Company

DEMONSTRATION/DELIVERY HOLD: Safety Recall 02S32-S1
All 2002 Model Year Rangers Built With the FX4 Off-Road Package
and a Manual Transmission—Rear Axle Replacement

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

PROMPTLY CORRECT

Promptly correct all affected vehicles on your dealer Online Involved Unit Listing available on QCDealer.com. Also, correct other affected vehicles identified in OASIS which are brought to your dealership.

DEALER-OWNER CONTACT

Low Volume Program: When you receive notification through CuDL (Customer Data Link), you should contact the owner and arrange for this service. Please note that our Coordination Center will advise owners that they will hear from you within the next two business days. For more information, see "Low Volume Announcement Letter" dated May 10,1999.

Immediately contact any of your affected owners whose names are not on your VIN list but are identified in OASIS. Give the owner a copy of the Owner Letter and schedule a service date.

Note: These dealer listings may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than in connection with this recall is a violation of law in several states/provinces/countries. Accordingly, you must limit the use of this listing to the follow-up necessary to complete this action.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

RENTAL VEHICLE

Ford Motor Company will pay for a rental vehicle while the vehicle is at the dealership for axle replacement. Fuel and insurance on rental vehicles will be at owner's expense. Enter the word "RENTAL" plus the number of days the vehicle was used in the Miscellaneous Expense area of the recall claim form.

© Copyright 2002 Ford Motor Company

DEMONSTRATION/DELIVERY HOLD: Safety Recall 02S32-S1
All 2002 Model Year Rangers Built With the FX4 Off-Road Package
and a Manual Transmission—Rear Axle Replacement

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Replace Rear Axle Housing	*02S32C*	*2.3 Hours*
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PART NUMBERS

Description	***Part Number***	***Quantity***
Rear Axle Housing	*3L5Z-4006-RA*	*1*
Bearing Assy Rear Wheel Kit	*E3TZ-1225-A*	*2*

ADDITIONAL PART NUMBERS

Description	***Part Number***	***Specification***	***Quantity***
SAE 75W-140 Synthetic Rear Axle Lubricant (or equivalent meeting specification)	*XY-75W-140-QL*	*WSL-M2C192-A*	*2.54 liters (5.37 pints)*
Additive Friction Modifier (or equivalent meeting specification)	*XL-3*	*EST-M2C1189-A*	*One (1) 4-ounce bottle*
Threadlock and Sealer (or equivalent meeting specification)	*EOAZ-19554-AA*	*WSK-M2G351-A5 (type II)*	
Silicone Rubber (or equivalent meeting specification)	*F7TZ-19554-AA*	*WSS-M4G320-A3*	
Premium Long Life Grease (or equivalent meeting specification)	*XG-1-C*	*ESA-M1C75-B*	
Black Paint - Low Temperature Anti Corrosion Coating (or equivalent meeting specification)	*PM-12-A*	*ESB-M2P230-B*	

© Copyright 2002 Ford Motor Company

DEMONSTRATION/DELIVERY HOLD: Safety Recall 02S32-S1
All 2002 Model Year Rangers Built With the FX4 Off-Road Package
and a Manual Transmission—Rear Axle Replacement

PARTS AVAILABILITY AND REQUIREMENTS

Part shipments done through the Low Volume Program by vehicle owner request will be communicated to dealers via CuDL and DOES II.

***CUSTOMER VEHICLES**: Rear axle housings are currently available and will be distributed using the Low Volume Program guidelines. Parts will be shipped to your dealership according to the procedures established for "Low Volume Programs". DO NOT order parts, except for dealer stock units, as referenced below (Refer to "Low Volume Programs").*

***Note:** When the customer calls the Coordination Center, the correct parts will be automatically sent to the Dealer. A CuDL and DOES II message will be sent to the Dealer confirming part shipment.*

***DEALER STOCK VEHICLES**: Correct all vehicles in stock before delivery. Orders can be placed immediately through the normal ordering process.*

ORDER INFORMATION

The DOR/COR for this program is 50273. This number identifies parts ordered for this recall through the Low Volume Coordination Center at (1-800-248-0186).

PARTS RETENTION

Follow the provisions of the Warranty and Policy Manual for “Parts Retention and Return Procedures”. *Original axle assemblies should be scrapped and done so in a manner that prevents reuse.*

DEALER PRICE

For latest prices, refer to DOES II or updated price book.

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

© Copyright 2002 Ford Motor Company