• **BRAKES—HYDROMAX LAMP ILLUMINATED WITH DIAGNOSTIC TROUBLE CODE (DTC) C1149 STORED IN MEMORY** • **ELECTRICAL—LAMP—HYDROMAX LAMP ILLUMINATED WITH DIAGNOSTIC TROUBLE CODE (DTC) C1149 STORED IN MEMORY**	**Article No. 02-1-5**

FORD: 2001 F-650, F-750

ISSUE

Some vehicles may exhibit a Hydromax light on with DTC C1149 stored in memory. This condition may occur after performing a self test on the GEM module. This may be caused by the software version of the Generic Electronic Module (GEM).

ACTION

Verify condition. If normal diagnostics cannot pinpoint the condition, replace the GEM module with an updated module. Refer to the following Service Information for details.

SERVICE PROCEDURE

After performing self test with scan tool, remove scan tool, and cycle ignition switch. Start vehicle twice. If the Hydromax light and warning chime go out, the condition is resolved, no other service action is required.

If the light and chime stay illuminated, then check Hydromax flow switch, Hydromax relay, and Hydromax feedback from Hydromax motor on service tool PID's. If Hydromax flow switch, Hydromax relay, and Hydromax feedback from Hydromax motor turn off after starting vehicle, replace the GEM 1C3Z-14B205-CA (engineering part number 1C3T-14B205-CB) level module with a 1C3Z-14B205-CB (engineering part number 1C3T-14B205-CC) level GEM module.

The updated level GEM module has a software update which corrects the DTC C1149 (Hydromax Flow Switch Circuit Failure). Refer to Workshop Manual section 419-10 for GEM module replacement.

PART NUMBER	PART NAME
1C3Z-14B205-CB	Generic Electronic Module (GEM)

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
020105A	Perform Self-Test, Start Vehicle Twice	0.3 Hr.
020105B	Verify Operation Of Components Listed In Service Procedure Then Replace G.E.M. (Generic Electronic Module)	1.2 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
14B205	42

OASIS CODES: 206000, 301000

Copyright © 2002 Ford Motor Company