- **NOISE—"HOOTING," "EEKING," OR "MOANING" NOISE COMING FROM CLUTCH WHEN SHIFTING GEARS**
- **CLUTCH—"HOOTING," "EEKING," OR "MOANING" NOISE COMING FROM CLUTCH WHEN SHIFTING GEARS**

Article No. 02-5-5

FORD: 1998-2002 RANGER

This article is being republished in its entirety to update the parts and model applications.

ISSUE

A "hooting," "eeking," or "moaning" noise may be emitted from the clutch when shifting into gears while the engine is running on some vehicles. This may be caused by the clutch pressure plate going into resonance when the clutch becomes 90% engaged. The clutch may be noisy but function and life are not affected.

ACTION

Remove existing clutch and pressure plate assemblies and replace with revised clutch and pressure plate assemblies. The revised clutch and pressure plate assemblies should reduce the possibility of noise. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

1. Verify noise is coming from clutch assembly.
2. Remove existing clutch assembly. Refer to the applicable Ranger Workshop Manual for removal and installation procedures.
3. **FOR 2.3L AND 2.5L MANUAL TRANSMISSION APPLICATIONS:** Replace existing clutch with new service clutch assembly 2L5Z-7550-AARM and replace existing pressure plate with new service pressure plate 2L5Z-7563-AA.

OR

4. **FOR 3.0L MANUAL TRANSMISSION APPLICATIONS:** Replace existing clutch assembly with new service clutch assembly 2L5Z-7550-BARM and replace existing pressure plate with new service pressure plate 2L5Z-7563-AA.
5. Verify with road test (normal clutch/shifting operations).

LABOR OPERATION CLAIMING CHART			
Operation	**Labor Description**	**Vehicle**	**Time**
020505A	Replace Clutch And Pressure Plate Assembly (Includes Time To Bleed Air From Hydraulic Clutch System After Repair)	2001-2002 4X2 2.3L	3.2
		1998-2001 4X2 2.5L	3.5
		1998-2002 4X2 3.0L	3.5
		1998-2002 4X4 3.0L	4.8

PART NUMBER	PART NAME
2L5Z-7550-AARM	Clutch - 2.3L/2.5L
2L5Z-7550-BARM	Clutch - 3.0L
2L5Z-7563-AA	Pressure Plate - 2.3L/2.5L/3.0L

OTHER APPLICABLE ARTICLES: NONE
SUPERSEDES: 98-26-10
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

DEALER CODING

BASIC PART NO.	CONDITION CODE
7550	42

OASIS CODES: 505200, 506000, 597997

Copyright © 2002 Ford Motor Company