• DRIVEABILITY—HESITATION DURING HARD SWEEPING RIGHT TURNS—AVAILABILITY OF UPDATED DESIGN FUEL PUMP • FUEL—HESITATION DURING HARD SWEEPING RIGHT TURNS—AVAILABILITY OF UPDATED DESIGN FUEL PUMP	**Article No. 01-13-4**

FORD: 2002 EXPLORER

MERCURY: 2002 MOUNTAINEER

ISSUE

A hesitation while making hard sweeping right hand turns (such as a highway on-ramp) may be felt on some vehicles. This may be caused by fuel pump cavitation due to fuel sloshing away from the filter sock in the fuel tank.

ACTION

If a vehicle comes in for this condition, check the fuel pressure. Check all fuel pump related electrical circuits. If a fuel pressure condition is verified, refer to the following Service Procedure for details.

SERVICE PROCEDURE

1. Attempt to verify if the fuel pressure drops during the event.
2. If a fuel pressure drop is verified, check all fuel pump related electrical wiring, connections and related systems.
3. If all other systems are ok, replace the fuel pump/sender assembly with a revised fuel pump/sender assembly. Refer to the parts listing for application.
4. Refer to the 2002 Explorer/Mountaineer Workshop Manual, Section 310-01, for removal and installation instructions.

PART NUMBER	PART NAME
1L2Z-9H307-KB	Fuel Pump - 4.0L Gas, North America W/5R55W Automatic Transmission
1L2Z-9H307-LB	Fuel Pump - All 4.6L, All 4.0L W/Manual Transmission And All Export Vehicles

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage And Emissions Warranty Coverage

OPERATION	DESCRIPTION	TIME
011304A	Replace Fuel Pump/Sender Assembly (Includes Time To Remove And Install Fuel Tank)	1.7 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
9H307	53

OASIS CODES: 404000, 611000, 611500

Copyright © 2001 Ford Motor Company