ELECTRICAL—AIR BAG LAMP ON WITH DIAGNOSTIC TROUBLE CODES (DTCS) B1994 AND/OR B1998—EXPLORER SPORT MODELS ONLY	Article No. 01-1-10

FORD: 2001 EXPLORER

ISSUE

Some 2001 Explorer Sport vehicles may exhibit the air bag lamp on with Diagnostic Trouble Codes (DTCs) B1994 and/or B1998 stored in memory. This may be due to high resistance or poor connections in the side air bag wiring harness circuits on vehicles equipped with or without side air bags.

ACTION

Install an overlay harness which incorporates soldered terminals and tin wiring. Order Side Air Bag Kit (1L2Z-14B455-AA). Installation instructions and illustrations are included in this kit.

NOTE

FOR VEHICLES EQUIPPED WITH SIDE AIR BAGS: RIGHT SIDE AIR BAG JUMPER HARNESS (XL2Z-14K155-CA) AND LEFT SIDE AIR BAG JUMPER HARNESS (XL2Z-14K155-AA) MUST ALSO BE ORDERED AND INSTALLED.

PART NUMBER	PART NAME
1L2Z-14B455-AA	Side Air Bag Kit
XL2Z-14K155-CA	Jumper Harness - Side Air Bag (RH)
XL2Z-14K155-AA	Jumper Harness - Side Air Bag (LH)

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
010110AB	Install Overlay Wire Harness And Side Air Bag Jumper Harnesses Located In Seats (Vehicles With Side Air Bags)	3.8 Hrs.
010110A	Install Overlay Wire Loom (Vehicles Without Side Air Bags)	2.2 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
14B455	42

OASIS CODES: 104000, 203200, 206000

Copyright © 2001 Ford Motor Company