- **IDLE—HIGH IDLE SPEEDS— THROTTLE STICKS AFTER STEADY STATE DRIVING IN EXTREME COLD AMBIENT TEMPERATURES—VEHICLES BUILT THROUGH 11/01/01 EQUIPPED WITH 5.4L ENGINE**
- **ENGINE—5.4L—PCV SYSTEM ICING— VEHICLES BUILT THROUGH 11/01/01**

Article No. 01-21-5

FORD: 1997-1998 EXPEDITION, F-150, F-250 LD
2000-2002 EXPEDITION, F-150

LINCOLN: 1998 NAVIGATOR

This article is being republished in its entirety to update the Model Year and vehicle applications and the Service Kit part number.

ISSUE

In rare instances, throttle sticking may occur on a few vehicles in very cold ambient temperatures after operating at steady speed or extended idle for a period of time. This may be due to ice build-up from moisture in the PCV gas on the throttle plate or throttle body.

ACTION

Verify the condition is not caused by throttle body sludging, throttle cable binding, or interference between an improperly positioned floor mat and accelerator pedal. If no other conditions are identified, check for evidence of PCV system backflow. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

Inspect the inside of the clean air tube at the PCV closure hose connection for presence of moisture, oil, or oily stains. If evidence of PCV system backflow is found, replace the PCV system with the revised PCV Service Kit, YL3Z-6A603-AA. Refer to the Instruction Sheet within the PCV Service Kit for Service Procedure.

PARTS USAGE CHART	
Model Year	**Parts Required**
1997-1998	Service Kit YL3Z-6A603-AA (Vacuum Harness Included)
2000-2002	Service Kit YL3Z-6A603-AA (Vacuum Harness In Kit Not Used) Order Vacuum Harness XL3Z-9E498-MA To Complement Kit Contents

NOTE
COMPRESSED NATURAL GAS UNITS ALSO REQUIRE F85Z-19C828-BA HOSE ASSEMBLY.

PART NUMBER	PART NAME
YL3Z-6A603-AA	PCV Service Kit - All
XL3Z-9E498-MA	Vacuum Harness - 2000-2002 Vehicles
F85Z-19C828-BA	Compressed Natural Gas (CNG) Hose Assembly

OTHER APPLICABLE ARTICLES: NONE
SUPERSEDES: 99-25-2
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage And Emissions Warranty Coverage

OPERATION	DESCRIPTION	TIME
012105A	Replace The PCV System With The Revised PCV Service Kit	2.0 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
6C324	42

OASIS CODES: 401000, 607400, 607500, 607600, 607700, 608400, 608500, 608600, 609400, 609500, 609600, 610500, 610600, 610700, 611000, 611500, 612000, 612500, 612600, 614500, 614600, 617400, 619400

Copyright © 2001 Ford Motor Company