• **DRIVEABILITY—MALFUNCTION INDICATOR LAMP (MIL) ILLUMINATED WITH DIAGNOSTIC TROUBLE CODE (DTC) P0442** • **ELECTRICAL—LAMP—MALFUNCTION INDICATOR LAMP (MIL) ILLUMINATED WITH DIAGNOSTIC TROUBLE CODE (DTC) P0442** • **TRANSMISSION—4R70W—SLIP/BUMP ON 1-2 SHIFT—HARSH 2-3 SHIFT—MALFUNCTION INDICATOR LAMP (MIL) ILLUMINATED WITH DTC P0442**	**Article No. 01-3-1**

FORD: 2001 MUSTANG

ISSUE

Some vehicles equipped with a 3.8L engine may exhibit a Malfunction Indicator Lamp (MIL) illuminated with Diagnostic Trouble Code (DTC) P0442. Vehicles equipped with a 4R70W automatic transmission may also exhibit a slip/bump on the 1-2 shift or a harsh 2-3 shift at hot operational temperatures. This may be caused by the calibration of the Powertrain Control Module (PCM).

ACTION

Repair any DTCs as necessary. If normal diagnostics fail to identify a concern, reprogram the PCM using the Worldwide Diagnostic System (WDS) as necessary. Refer to the following PCM Calibration Information Chart.

PCM CALIBRATION INFORMATION

Application	Old Part Number (-12A650-)	Tear Tag	New Part Number (-12A650-)	Old Calibration	New Calibration	NGS/WDS Qualifier
ULEV (Ultra Low Emission Vehicle) A/T	1R3F-NC	N/A	1R3Z-ND	1ZE13P0506	1ZE13P0510	N/A Use WDS
ULEV (Ultra Low Emission Vehicle) M/T	1R3F-PC	N/A	1R3Z-PD	1ZE23P0506	1ZE23P0510	N/A Use WDS
LEV (Low Emission Vehicle) A/T	1R3F-BC	N/A	1R3Z-BD	1ZE13P0A06	1ZE13P0A10	N/A Use WDS
LEV (Low Emission Vehicle) M/T	1R3F-DC	N/A	1R3Z-DD	1ZE23P0A06	1ZE23P0A10	N/A Use WDS

Obtain an Authorized Modifications Decal (FPS 8262 - obtainable through DOES II, 25/pkg) and list the date, dealer number, and summary of modifications performed. Select a prominent place adjacent to the Vehicle Emission Control Information Decal suitable for installing the Authorized Modifications Decal. Clean the area, install the decal, and cover it with a clear plastic decal shield.

Copyright © 2001 Ford Motor Company

AUTHORIZED MODIFICATIONS

THE FOLLOWING MODIFICATIONS HAVE BEEN MADE:
Reprogrammed Powertrain Control Module
(PCM) Per TSB 01-3-1
THESE MODIFICATIONS HAVE BEEN APPROVED, AS APPROPRIATE, BY EPA AND CARB.
DEALER NUMBER: DATE:
CHANGE AUTHORITY:
FPS 8262 9/78 FORD MOTOR COMPANY PRINTED IN U.S.A.

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 501000, 502000, 504000, 698298