• **DRIVEABILITY—MALFUNCTION INDICATOR LAMP (MIL) WITH P0316 WHEN USING WINTER BLEND REFORMULATED FUELS AT TEMPERATURES ABOVE 50 DEGREES F (10 DEGREES C) DURING WINTER MONTHS—ROUGH OR ROLLING IDLE AFTER HOT SOAK RESTART P0191** • **TRANSAXLE—AX4S—1-2 UPSHIFT HESITATION COLD—3.0L 2V/FFV ENGINES**	**Article No. 02-22-3**

FORD: 2002 TAURUS

MERCURY: 2002 SABLE

ISSUE

Some 3.0L 2V and FFV vehicles may exhibit any of the following:

- Hot soak restart rough idle
- Idle dip
- Intermittent P0191 DTC
- Check engine light with a P0316 DTC with winter blend reformulated fuels in 50° F (10° C) and above temperatures
- AX4S equipped vehicles a 1-2 upshift hesitation or sag during cold engine/transmission operation

This may be caused by the Calibration of the Powertrain Control Module (PCM).

ACTION

Verify the condition and symptoms as stated in the Issue and reprogram the PCM to the latest calibration level. Refer to the following Service Information for details.

SERVICE PROCEDURE

Verify the condition and symptoms as stated in the Issue and reprogram the PCM to the latest calibration level. Refer to the following PCM Calibration Information chart for details.

For vehicles exhibiting a P0316 code, verify the following:

Follow normal diagnostics for the P0316 code and repair any faulty components which could have caused the misfire. If freeze frame data indicates the P0316 occurred after a hot soak and climate temperature during winter months is 50° F (10° C) and above in the northern United States and Canada which are using winter blend reformulated fuels, replace the fuel pump with part number 3F1Z-9H307-AA for 2V or 3F1Z-9H307-BA for FFV.

Copyright © 2002 Ford Motor Company

Article No. 02-22-3 Cont'd.

PCM CALIBRATION INFORMATION							
Application	Old Part Number (12A650)	Old Tear Tag	New Part Number (12A650)	New Tear Tag	Old Calibration	New Calibration	WDS/NGS Qualifier
2002 3.0L 2V Gas AX4S	2F1A-SB	UVA1	2F1Z-SE	UVA4	2DD13S0505	2DD13S0511	WDS B 20.12 Release or Later
2002 3.0L 2V Gas AX4S	2F1A-SC	UVA2	2F1Z-SE	UVA4	2DD13S0506	2DD13S0511	WDS B 20.12 Release or Later
2002 3.0L 2V Gas AX4N	2F1A-RC	VBP2	2F1Z-RE	VBP4	2DD13N0506	2DD13N0511	WDS B 20.12 Release or Later
2002 3.0L 2V FFV AX4S	2F1A-PC	RD12	2F1Z-PE	RDI4	2DD13V0506	2DD13V0511	WDS B 20.12 Release or Later
2002 3.0L 2V FFV AX4N	2F1A-AHA	HUE0	2F1Z-AHC	HUE2	2DD13F0500	2DD13F0511	WDS B 20.12 Release or Later
2002 3.0L 2V Gas AX4N GCC	2F1A-VB	VQA1	2F1Z-VD	VQA3	2DD13U0G05	2DD13U0G11	WDS B 20.12 Release or Later
2002 3.0L 2V Gas AX4S	2F1A-DE	RBG4	2U7Z-BLA	YMJ0	2DD12S0508	2DD12S0511	WDS B 20.12 Release or Later
2002 3.0L 2V Gas AX4S	2F1A-DF	RBG5	2U7Z-BLA	YMJ0	2DD12S0510	2DD12S0511	WDS B 20.12 Release or Later
2002 3.0L 2V Gas AX4S	2F1A-DG	RBG6	2U7Z-BLA	YMJ0	2DD12S0511	2DD12S0511	WDS B 20.12 Release or Later
2002 3.0L 2V Gas AX4N	2F1A-CE	TMU4	2U7Z-BMA	MCN0	2DD12N0508	2DD12N0511	WDS B 20.12 Release or Later
2002 3.0L 2V Gas AX4N	2F1A-CF	TMU5	2U7Z-BMA	MCN0	2DD12N0510	2DD12N0511	WDS B 20.12 Release or Later
2002 3.0L 2V Gas AX4N	2F1A-CG	TMU6	2U7Z-BMA	MCN0	2DD12N0511	2DD12N0511	WDS B 20.12 Release or Later
2002 3.0L 2V Gas AX4S	2F1A-AC	WWK2	2U7Z-BNA	NFH0	2DD1FS0506	2DD1FS0507	WDS B 20.12 Release or Later
2002 3.0L 2V Gas AX4S	2F1A-AD	WWK3	2U7Z-BNA	NFH0	2DD1FS0507	2DD1FS0507	WDS B 20.12 Release or Later
2002 3.0L 2V Gas AX4N GCC	2F1A-TA	OTT0	2U7Z-BPA	PKM0	2DD1G20G00	2DD1G20G11	WDS B 20.12 Release or Later
2002 3.0L 2V Gas AX4N GCC	2F1A-TB	OTT1	2U7Z-BPA	PKM0	2DD1G20G05	2DD1G20G11	WDS B 20.12 Release or Later
2002 3.0L 2V Gas AX4N GCC	2F1A-TC	OTT2	2U7Z-BPA	PKM0	2DD1G20G10	2DD1G20G11	WDS B 20.12 Release or Later
2002 3.0L 2V Gas AX4N GCC	2F1A-TD	OTT3	2U7Z-BPA	PKM0	2DD1G20G11	2DD1G20G11	WDS B 20.12 Release or Later

Obtain an Authorized Modifications Decal (FPS 8262 - obtainable through DOES II, 25/pkg) and list the date, dealer number, and summary of modifications performed. Select a prominent place adjacent to the Vehicle Emission Control Information Decal suitable for installing the Authorized Modifications Decal. Clean the area, install the decal, and cover it with a clear plastic decal shield.

AUTHORIZED MODIFICATIONS

THE FOLLOWING MODIFICATIONS HAVE BEEN MADE:
Reprogrammed Powertrain Control Module
(PCM) Per TSB 02-22-3
THESE MODIFICATIONS HAVE BEEN APPROVED, AS APPROPRIATE, BY EPA AND CARB.
DEALER NUMBER: DATE:
CHANGE AUTHORITY:
FPS 8262 9/78 FORD MOTOR COMPANY PRINTED IN U.S.A.

PART NUMBER	PART NAME
3F1Z-9H307-AA	Fuel Pump - 2V Gas
3F1Z-9H307-BA	Fuel Pump - FFV

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 501000, 607000, 607400, 608000, 608400, 609000, 609400, 609500, 609600, 610000, 610500, 611000, 611500, 618400, 698298

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle.