• **MALFUNCTION INDICATOR LAMP (MIL) ILLUMINATED—DIAGNOSTIC TROUBLE CODES (DTCS) P0135, P0141, P0155, P0161, AND P0455—NO DRIVEABILITY CONCERNS —VEHICLES WITH 5.4L ENGINE** • **LAMP—MALFUNCTION INDICATOR LAMP (MIL) ILLUMINATED—DIAGNOSTIC TROUBLE CODES (DTCS) P0135, P0141, P0155, P0161, AND P0455—NO DRIVEABILITY CONCERNS—VEHICLES WITH 5.4L ENGINE** • **POWERTRAIN CONTROL MODULE (PCM)—REPROGRAM—VEHICLES WITH 5.4L ENGINES**	**Article No. 99-25-3**

FORD: 2000 EXCURSION, F-250

ISSUE

The Malfunction Indicator Lamp (MIL) may illuminate with Diagnostic Trouble Code (DTC) P0455 stored in memory if the fuel cap is loose or off. There could also be DTCs P0135, P0141, P0155, or P0161 stored in memory and no driveability concerns on some vehicles. These concerns may be due to Powertrain Control Module (PCM) calibration (OBDII monitors not completing frequently enough). This TSB article has been coded on OASIS to enable this service repair to be performed on all referenced calibrations.

ACTION

Reprogram the PCM with the latest level calibration using Worldwide Diagnostic System (WDS), Service Bay Diagnostic System (SBDS), or New Generation Star (NGS) Tester. Refer to the following PCM Reprogramming Information Chart to identify the appropriate calibration.

NOTE

DEALERS SHOULD INSTRUCT CUSTOMERS TO CHECK THE FUEL CAP IN SUCH SITUATIONS FOR PROPER INSTALLATION.

PCM REPROGRAMMING INFORMATION		
Application	**Tear Tag Number**	**NGS/SBDS Qualifier**
Excursion	XXFx, EKGx	0L114D0B CALIBRATION
Excursion	HDAx	0L114N0A CALIBRATION
F-250	FVRx	0F714D0B CALIBRATION
F-250	CPYx	0F714N0A CALIBRATION

Obtain an Authorized Modifications Decal (FPS 8262 - obtainable through DOES II, 25/pkg) and list the date, dealer number, and summary of modifications performed. Select a prominent place adjacent to the Vehicle Emission Control Information Decal suitable for installing the Authorized Modifications Decal. Clean the area, install the decal, and cover it with a clear plastic decal shield.

AUTHORIZED MODIFICATIONS

THE FOLLOWING MODIFICATIONS HAVE BEEN MADE:
Reprogrammed Powertrain Control Module
(PCM) per TSB 99-25-3.
THESE MODIFICATIONS HAVE BEEN APPROVED, AS APPROPRIATE, BY EPA AND CARB.
DEALER NUMBER: **DATE:**
CHANGE AUTHORITY:
FPS 8262 9/78 **FORD MOTOR COMPANY** **PRINTED IN U.S.A.**

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage And Emissions Warranty Coverage

OPERATION	DESCRIPTION	TIME
992503A	Reprogram Powertrain Control Module (PCM)	0.6 Hr.

DEALER CODING

BASIC PART NO.	CONDITION CODE
RECALEM	42

OASIS CODES: 101000, 102000, 103000, 104000, 105000, 106000, 107000, 108000, 110000, 111000, 112000, 190000, 201000, 201100, 201200, 202000, 203000, 203100, 203200, 204000, 204100, 204200, 205000, 206000, 207000, 208000, 208100, 208200, 208300, 208999, 290000, 301000, 302000, 303000, 304000, 305000, 306000, 307000, 390000, 401000, 402000, 403000, 404000, 490000, 497000, 499000, 501000, 502000, 503000, 504000, 505000, 505200, 506000, 507000, 508000, 509000, 510000, 590000, 597997, 601300, 602300, 603300, 607000, 607400, 607500, 607600, 607700, 608000, 608400, 608500, 608600, 609000, 609400, 609500, 609600, 610000, 610500, 610600, 610700, 611000, 611500, 612000, 612500, 612600, 613000, 613400, 613500, 613700, 614000, 614500, 614600, 615000, 615500, 615600, 617400, 618400, 619400, 621000, 622000, 623000, 690000, 698298, 701000, 702000, 702100, 702200, 702300, 703000, 703100, 703200, 703300, 703400, 790000