| | |
|---|---|
| • **LACK OF POWER—UNDER A LOAD, AT CRUISE OR ON ACCELERATION—VEHICLES EQUIPPED WITH 7.3L DIT ENGINE ONLY—PRODUCED BEFORE 11/25/2000 ONLY**<br>• **ENGINE—7.3L DIT—LACK OF POWER UNDER A LOAD, AT CRUISE OR ON ACCELERATION—VEHICLES PRODUCED BEFORE 11/25/2000 ONLY** | **Article No. 01-9-5** |

**FORD:** 1999-2001 SUPER DUTY F SERIES
2000-2001 EXCURSION

## ISSUE

A lack of power under a load, at cruise or on acceleration may occur on some vehicles built before 11/25/2000 equipped with the 7.3L DIT engine. This may be caused by a collapsed air filter element or defective air box/lid.

## ACTION

Verify condition. If normal diagnostics cannot pinpoint condition, replace the air cleaner assembly and element with revised 3 ″ panel element and revised air lid and air box, 1C3Z-9600-AA. Refer to the appropriate Workshop Manual, Section 303-12 for air cleaner removal and installation details.

| PART NUMBER | PART NAME |
|---|---|
| 1C3Z-9600-AA | Air Cleaner Assembly |

**OTHER APPLICABLE ARTICLES:** NONE
**SUPERSEDES:** 98-16-11, 99-6-4
**WARRANTY STATUS:** Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage And Emissions Warranty Coverage

| OPERATION | DESCRIPTION | TIME |
|---|---|---|
| 010905A | Replace Air Cleaner (Includes Time For Final Test Drive) | 0.9 Hr. |

**DEALER CODING**

| BASIC PART NO. | CONDITION CODE |
|---|---|
| 9C662 | 42 |

**OASIS CODES:** 614000, 614500, 614600

Copyright © 2001 Ford Motor Company