QUIT ON ROAD—DIAGNOSTIC TROUBLE CODE (DTC) C1755 STORED IN MEMORY—SERVICE TIP—ELECTRIC VEHICLES ONLY	Article No. 00-11-3

FORD: 1998-2000 RANGER

ISSUE

The Service Manual Page 414-03A-69 Pinpoint Test A: DTC C1755 Power Limit Shutdown Fault does not adequately diagnose the concern. Steps A-1, A-2 and A-3 make no mention of a possible lack of coolant flow through either the Traction Inverter Module (TIM) or the motor/transaxle. Such a condition with the current diagnosis could lead the technician to an incorrect repair and unnecessary parts being replaced.

ACTION

Refer to the following Service Procedure when the subject concern is encountered.

SERVICE PROCEDURE

1. The TIM sets Diagnostic Trouble Code (DTC) C1755 when the vehicle is shut down for one of four reasons.
   a. The temperature protection in the TIM has limited current to zero amps.
   b. The Battery Control Module (BCM) sent the TIM a request to limit source current to zero.
   c. A vehicle over-speed shutdown request from the motor/transaxle.
   d. Lack of coolant flow causing a quick rise in temperature within the TIM.
2. The DTCs must be retrieved from the Interface Adapter Assembly (IAA) module before retrieving DTCs from the TIM. If IAA module DTC C1774 coolant temperature sensor out-of-range occurs, refer to Section 303-03 Pinpoint Test A: DTC C1774 Coolant Temperature Sensor Out-of-Range before proceeding.
3. If DTC C1854 occurs during DTC retrieval, refer to Section 303-14 before proceeding.
4. Retrieve DTC codes from TIM. A possible DTC C1755 may be present. Record and retain for future reference. If any other DTCs are present, proceed with normal diagnostic procedures for that DTC.
5. Retrieve DTC codes from BCM. If any other DTCs are present, proceed with normal diagnostic procedures for that DTC. Refer to the Workshop Manual, Page 303-03-5 Pinpoint Test B: Coolant Pump Does Not Operate. Perform complete Pinpoint Test Section.

NOTE

THE IAA CONTROLS OPERATION OF THE ELECTRIC COOLANT PUMP. THE IAA ENERGIZES THE PUMP WHENEVER THE IGNITION KEY IS IN THE ON POSITION AND DURING TRACTION BATTERY CHARGING IF THE DC/DC MODULE IS CHARGING THE AUXILIARY 12-VOLT BATTERY. THERE IS A POSSIBILITY THAT THE COOLANT PUMP IS INTERMITTENT. AN AUDIBLE NOISE SHOULD BE HEARD WHEN THE KEY IS ON (DO NOT ENABLE THE ELECTRIC MOTOR), OR WHEN THE VEHICLE IS ON-PLUG AND THE AUXILIARY BATTERY IS BEING CHARGED BY THE DC/DC CHARGER.

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 203000, 402000, 607000, 607400, 607500, 607600, 614000, 614500, 614600, 698298