Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

August 2000

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Special Service Instruction 00T06-S1: Certain 2001 Model Year Escape 4x4 Vehicles – Rear Driveshaft Replacement and Rear Differential Leak

Re: Special Service Instruction 00T06: Certain 2001 Model Year Escape Vehicles – Rear Driveshaft Replacement, dated August, 2000

OASIS :	Yes
OWNER LIST:	**No**
OWNER LETTERS:	**No**
PARTS RETURN:	See Attachment II
PROGRAM TERMS:	Through applicable 36 month / 36,000 miles warranty coverage only

REASON FOR SUPPLEMENTAL INFORMATION – ADDITIONAL UNITS ADDED; BUILD DATE RANGE EXPANDED

An additional 129 units have been identified as being affected by Special Service Instruction 00T06 and the build date range has been expanded to include vehicles built from January 31, 2000. Note change to affected vehicles in the following section, AFFECTED VEHICLES.

Also, the Technical Instructions have been updated to include a rear differential leak inspection and re-seal repair, in addition to rear driveshaft replacement. Refer to Attachment III 00T06-S1.

AFFECTED VEHICLES

Certain 2001 Model Year Escape vehicles built at the Kansas City Assembly Plant from **January 31, 2000** through July 26, 2000.

REASON FOR THIS SPECIAL SERVICE INSTRUCTION

Certain affected vehicles were built with a rear driveshaft that was produced with a CV joint shaft that may interfere with the CV joint boot. The interference may cause the CV joint boot to develop a hole, allowing contaminants to enter the CV joint, which may lead to CV joint failure. If the described condition exists, the contamination can lead to CV joint corrosion and a significant NVH concern.

Additionally, affected vehicles may experience a leak at the joint between the rear differential and the rotary blade coupling (RBC) housing. Inconsistent installation procedures of the mass damper to rotary blade coupling are identified as the cause of the leak.

SPECIAL SERVICE INSTRUCTION

Dealers are to inspect the vehicle for a leak at the specified rear differential joint and, if necessary, reseal the joint and properly re-torque the mass damper to the rotary blade coupling housing. Additionally, all affected vehicles require the replacement of the vehicle's rear driveshaft.

OWNER NOTIFICATION

There will be no owner notification from Ford Motor Company; this is a Special Service Instruction as part of applicable 36 month / 36,000 mile warranty service. Dealers should inform owners upon completion of this Special Service Instruction that their vehicle's rear differential was inspected for a leak, resealed if necessary and the vehicle's rear driveshaft was replaced to ensure customer satisfaction.

ATTACHMENTS

Attachment I:	Administrative Information
Attachment II:	Labor Allowances
Attachment III:	Technical Information, Supplement 00T06-S1

QUESTIONS?

Claims Information:	1-800-423-8851
Other Program Questions:	1-800-325-5621

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

SPECIAL SERVICE INSTRUCTION: 00T06-S1
Certain 2001 Model Year Escape Vehicles – Rear Driveshaft Replacement and Rear Differential Leak

OASIS

You must use OASIS to determine if a vehicle is eligible for this Special Service Instruction.

PLEASE NOTE

Correct all vehicles in stock before delivery.

PROMPTLY CORRECT

Promptly correct all affected vehicles at your dealership and other eligible vehicles which are brought to your dealership within the applicable 36 month / 36,000 mile warranty coverage period.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII Manual for claims preparation and submission information.

NOTE: Prepare and submit claims on the ACESII **warranty** screen rather than the ACESII recall screen.

- Use code information shown below:
  - Program Code – 00T06
  - Causal Component – 4602
  - Condition Code – 12
  - Labor Operation – Refer to Attachment II

MATERIAL ALLOWANCE

Description	Part Number	Material Allowance
RTV Sealant	F7TZ-19554-AA	Dealers may claim $6.56 per claim for the quantity of RTV Sealant used on each vehicle. **To claim this allowance, use Miscellaneous Code "OTHER".**

SPECIAL SERVICE INSTRUCTION: 00T06-S1
Certain 2001 Model Year Escape Vehicles – Rear Driveshaft Replacement and Rear Differential Leak

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Inspect Rear Differential for Leak and Replace Rear Driveshaft	00T06B	0.8 hours
Inspect Rear Differential for Leak, Replace Rear Driveshaft, Reseal Rear Differential and Re-Torque Mass Damper	00T06C	1.2 Hours

PARTS REQUIREMENTS

Parts Ordering Information

Parts will not be direct shipped for this recall. Order your parts requirement through the Recall Hotline (1-800-325-5621). Parts will be shipped Priority Next Day delivery.

Part Number	Quantity per Repair	Description
YL8Z-4602-BH	1	Driveshaft, Rear
YL8Z-4N272-AA	4	Bolt, Retainer (Sold 4 bolts to a package. One package will complete 1 vehicle.)
W705891-S301	2	Nuts, Center Bearing Retaining (Sold 4 nuts to a package. One package will complete 2 vehicles.)
F7TZ-19554-AA	Partial	RTV Sealant (One tube will complete 2 vehicles. Allowance of $ 6.56 per repair is provided.)
XY80W90-QL	1 quart	Gear Lube

NOTE: Removed parts must be mutilated and properly scrapped to prevent their use on another vehicle.

ORDER INFORMATION DOR/COR

DOR/COR number 50175 identifies parts ordered for this campaign through the Recall Hotline (1-800-325-5621).

DEALER PRICE

For latest prices, refer to:

- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.