- **DRIVEABILITY—DIAGNOSTIC TROUBLE CODES (DTCS) P0171/P0174 STORED IN MEMORY—VEHICLES EQUIPPED WITH 3.8L ENGINE**
- **MALFUNCTION INDICATOR LAMP (MIL)—MIL ILLUMINATED WITH DIAGNOSTIC TROUBLE CODES (DTCS) P0171/P0174 STORED IN MEMORY—VEHICLES EQUIPPED WITH 3.8L ENGINE**
- **LAMP—MALFUNCTION INDICATOR LAMP (MIL) ILLUMINATED WITH DIAGNOSTIC TROUBLE CODES (DTCS) P0171/P0174 STORED IN MEMORY—VEHICLES EQUIPPED WITH 3.8L ENGINE**

Article No. 01-1-12

FORD: 1999-2000 WINDSTAR

ISSUE

Some vehicles may exhibit a check engine light on and lean Diagnostic Trouble Codes (DTCs) P0171/P0174 stored in memory. This may be caused by a loose vacuum line fitting on the fuel pressure regulator.

ACTION

If diagnosis leads to the vacuum line from the intake manifold to the fuel pressure regulator that is loose at the manifold due to oil contamination, replace the vacuum line with a new piece and install a new design LH valve cover. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

1. Perform normal diagnostics for P0171/P0174 check engine light concerns.
2. Inspect the vacuum line from the intake manifold to the fuel pressure regulator and replace Vacuum Line (XF2Z-9E498-DA) if damaged. Also install a new LH Valve Cover (XF2Z-6582-CA).
3. Check all potential lean contributors including:
   - Correct Baro (Mass Air Flow (MAF)) reading (150 Hz+ at sea level)
   - Relative injector flow between all injectors
   - Vacuum leaks (brake booster, vacuum hoses/plumbing, Vapor Management Valve (VMV), intake manifold vacuum nipples/gaskets)
4. Check Heated Exhaust Gas Oxygen (HEGO) switching, wiring, and fuel pump pressure/volume.
5. Compare short and long term fuel trims to verify fuel control condition.

NOTE

IF NO CONTRIBUTORS EXIST, THE CONDITION COULD BE DUE TO WARM AMBIENT TEMPERATURES AND THE USE OF WINTER GRADE FUELS WHICH HAVE VERY HIGH VOLATILITY AND BOIL IN THE FUEL LINES (VAPOR LOCK) DURING A SHORT HOT SOAK. OXYGENATED FUELS WILL AGGRAVATE THIS CONDITION. IF NON-OXYGENATED FUEL IS NOT AVAILABLE, USE MID/HIGH OCTANE FUELS WHICH HAVE LOWER VOLATILITY AND MAY HELP ALLEVIATE THE CONDITION.

PART NUMBER	PART NAME
XF2Z-9E498-DA	Vacuum Line Fitting
XF2Z-6582-CA	Valve Cover - LH

OTHER APPLICABLE ARTICLES: 00-21-8
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 404000, 698298

Copyright © 2001 Ford Motor Company