COOLING SYSTEM—MEDIUM DUTY TRUCKS WITH OVERHEAT CONDITION—VEHICLES WITH 26 INCH COOLING FAN—CUAUTITLAN BUILT VEHICLES ONLY

Article No. 01-12-7

FORD: 1993-1999 F-600, F-700, F-800
2000-2001 F-650, F-750

ISSUE

Some vehicles equipped with 26 inch diameter fans may exhibit an engine overheat condition. This may be caused by early failure of the engine cooling viscous fan clutch.

ACTION

If a malfunctioning fan clutch is determined to be causing engine overheating, and normal diagnostics cannot pinpoint the condition, replace the fan clutch using a new service fan clutch 1C4Z-8A616-CA. The old fan clutch service part number is F3HZ-8A616-B, with engineering part number F3HT-8A616-BA.

- 1993-1999 model years also require a new service fan, YC3Z-8600-CA. The existing F3HZ-8600-A fan must NOT be used with the new 1C4Z-8A616-CA fan clutch. Remove and discard the old fan.
- 2000-2001 model years DO NOT require a fan replacement, only fan clutch.

Refer to the following Service Procedure for details.

SERVICE PROCEDURE

Fan and Clutch Special Service Tools Required

- Fan and Clutch Pulley Holder - Tool Number T84T-6312-C or equivalent
- Fan Clutch Nut Wrench - Tool Number T83T-6312-B or equivalent

REMOVAL

Refer to the appropriate model year Workshop Manual for removal procedures.

NOTE
THE FAN CLUTCH ASSEMBLY HAS A LEFT-HAND THREAD AND MUST BE ROTATED CLOCKWISE FOR REMOVAL.

NOTE
DO NOT HAMMER ON THE FAN CLUTCH TO REMOVE IT, AS DOING SO CAN DAMAGE THE FAN PULLEY BEARINGS ON THE ENGINE.

1. For 1993-1999 model year vehicles, discard the fan and clutch.
2. For 2000-2001 model year vehicles, remove the nuts attaching the fan to the clutch, discard the clutch, and transfer the fan blade to the new fan clutch. Verify that the blade part number found on the metal hub and/or on the front surface of the one of the blades is YC35-8600-CA. If not, discard the fan also.

INSTALLATION

Refer to the appropriate model year Workshop Manual for installation procedures.

NOTE
THE FAN CLUTCH ASSEMBLY HAS A LEFT-HAND THREAD AND MUST BE ROTATED COUNTER-CLOCKWISE FOR TIGHTENING.

PART NUMBER	PART NAME
1C4Z-8A616-CA	Fan Clutch - Engine Cooling

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: Eligible Under The Provisions Of Basic Warranty Coverage

OPERATION	DESCRIPTION	TIME
011207A	Replace Engine Cooling Fan Clutch	1.0 Hr.

DEALER CODING

BASIC PART NO.	CONDITION CODE
8A616	42

OASIS CODES: 402000, 622000, 702000, 702100, 703000

Copyright © 2001 Ford Motor Company