FRONT ELECTRONIC MODULE RECONFIGURATION

AFFECTED VEHICLES: CERTAIN 1999 AND 2000 MODEL YEAR WINDSTAR VEHICLES

OVERVIEW

The affected vehicles will require a reconfiguration of the front electronic module (FEM). This will be accomplished using one of the following methods:

- New Generation Star (NGS) Tester with the Ford Service Function Card, Version 7.1.
- Worldwide Diagnostic System (WDS) with software release B-11.

SERVICE PROCEDURE

RECONFIGURING WITH NGS

1. Insert the Service Function Card into the NGS tester.
2. Connect the NGS tester to the vehicle data link connector (DLC).
3. Select Service Bay Functions.
4. Select GEM-Generic Electronic Module.
5. Select Customer Preference Items.
6. Select Module Option Content.
7. Select 99-00 Windstar.
8. Select Ambient Temperature-Enable. Wait until you receive a confirmation screen.
9. Disconnect the NGS and remove the Service Function Card.

RECONFIGURING WITH WDS

1. Initialize the WDS.
2. Select 16 Pin.
3. Select All-Except Those Below.
4. Follow on-screen instructions for hooking up the WDS to the vehicle.
5. Make the appropriate selection for Traction Assist Equipped (Yes or No).
6. Select Yes to confirm the Vehicle Specifications screen.
7. Enter VIN, Repair Order # and Odometer reading (if required).
8. Select Exit on the Network screen.
9. Select the Tools tab at the top of the screen.
10. Select Module Programming.
11. Select Programmable Parameters.
12. Select outside temperature.
13. Select outside air temperature display – (FEM) = not equipped.
14. Select equipped (This will change the previous line/step from = not equipped to = equipped).
15. Exit the session. Disconnect the WDS from the vehicle.

Ford Motor Company

CPR © 2000 FORD MOTOR COMPANY
DEARBORN, MICHIGAN 48121
12/00