STEERING—POWER STEERING FLUID LEAK FROM RACK AND PINION END SEALS—REVISED RACK AND PINION UNIT	Article No. 01-5-6

FORD: 1998-2001 WINDSTAR

ISSUE

Some vehicles may exhibit a power steering fluid leak from the end seals of the steering rack and pinion. This may be caused by fluid leaking past the main shaft at the end seals.

ACTION

Replace the power steering rack with a revised steering rack (-3504-). Refer to the following Service Procedure for details.

SERVICE PROCEDURE

1. Perform normal diagnostics for power steering leaks per Section 211-00 of the appropriate model year Workshop Manual for steering systems.
2. Confirm that the steering gear is leaking fluid from the end seals.
3. Replace the steering gear with a revised unit.
4. Bleed all of the air from the steering system using the bleed procedure in Section 211-00 of the Workshop Manual.
5. Confirm that there are no leaks remaining in the steering system.

PART NUMBER	PART NAME
F88Z-3504-ACRM	Steering Gear (1998 Model Year)
XF2Z-3504-BDRM	Steering Gear (1999-2000 Model Years)
1F2Z-3504-ABRM	Steering Gear (2001 Model Year)

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 303000

Copyright © 2001 Ford Motor Company