CLUTCH—CLUTCH WILL NOT FULLY DISENGAGE—CLUTCH BLEEDS OFF WHEN DEPRESSED VEHICLES BUILT 3/15/1999 THROUGH 12/2/1999

Article No. 01-5-9

FORD: 2000 F-650, F-750

This article is being republished in its entirety to update the part numbers.

ISSUE

Some vehicles may exhibit a clutch pedal that when pressed to the floor, may not return or release clutch. The clutch slave cylinder and/or master cylinder seal and bore may be contaminated with dirt, causing premature failure.

ACTION

Install new clutch kit assembly (reservoir, master cylinder, slave cylinder, clutch tube). Refer to the following Service Procedure for details.

SERVICE PROCEDURE

1. Obtain Clutch Service Kit (review engine type).
   - For Caterpillar and Cummins engines, use Clutch Kit YC3Z-7C522-AB.
   - For Navistar 7.3L engine, use Clutch Kit YC3Z-7C522-BB.
2. Replace all clutch components included with kit.
3. For clutch kit installation, follow instruction in Workshop Manual, Section 308-02, “Clutch Controls, Removal and Installation.”

NOTE

MAKE SURE THE CLUTCH MASTER CYLINDER RESERVOIR IS FULL DURING THE BLEEDING PROCEDURE TO PREVENT AIR FROM ENTERING THE CLUTCH HYDRAULIC SYSTEM. BLEED THE HYDRAULIC SYSTEM AS FOLLOWS:

- Fill the clutch master cylinder reservoir to the fill line.
- Slowly depress and release the clutch pedal five to ten times or until no air bubbles are present at the clutch master cylinder reservoir.
- Recheck clutch master cylinder fluid level.

PART NUMBER	PART NAME
YC3Z-7C522-AB	Clutch Kit (Caterpillar And Cummins Engines)
YC3Z-7C522-BB	Clutch Kit (Navistar 7.3L Engine)

OTHER APPLICABLE ARTICLES: NONE
SUPERSEDES: 00-21-1
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
010509A	Install New Clutch Kit Assembly (Reservoir, Master Cylinder, Slave Cylinder, Clutch Tube)	1.1 Hr.

DEALER CODING

BASIC PART NO.	CONDITION CODE
7C522	49

OASIS CODES: 505000, 506000

Copyright © 2001 Ford Motor Company