ELECTRICAL—RADIO—SPEAKER WHINE NOISE—VEHICLES WITH "ULTIMATE" PIONEER RADIO SYSTEM PRODUCED ON OR AFTER 3/4/2002 ONLY

Article No. 02-17-3

FORD: 2002 EXPLORER SPORT TRAC

ISSUE

Some vehicles built on or after 3/4/02, equipped with the Pioneer "Ultimate" 450 watt audio system may exhibit a whine noise from the speakers when using the radio or the CD. The noise changes with engine RPM and is worse with various electrical loads on. This may be due to electrical interference induced into the system by the routing of the power and grounds leads.

ACTION

To correct the whine noise, the power/ground wiring must be rerouted. To accomplish this, some of the wiring in the vehicle harness will be disabled and an overlay harness will be installed. Order Overlay Harness Kit, 2L2Z-19B113-AA.

SERVICE PROCEDURE

Refer to the Service Procedures & Illustrations on the instruction sheet included in the kit.

PART NUMBER	PART NAME
2L2Z-19B113-AA	Overlay Wire Harness Kit

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
021703A	Install Overlay Harness Kit	1.3 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
19B113	43

OASIS CODES: 203000, 203100, 203200, 207000

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle.

Copyright © 2002 Ford Motor Company