BODY—FUEL FILLER DOOR—POOR FIT—REMOTE FUEL DOOR POPS OPEN—SERVICE ADJUSTMENT TIPS	Article No. 01-18-9

FORD: 2001 CROWN VICTORIA

MERCURY: 2001 GRAND MARQUIS

ISSUE

Some vehicles may exhibit a fuel filler door that does not fit correctly or the fuel door may inadvertently pop open. A remote fuel filler door feature was added to the Crown Victoria and Grand Marquis vehicle lines for the 2001 model year. This may be caused by an out of adjustment fuel door or striker.

ACTION

Poor fit of the fuel filler door may be characterized by a visually unappealing alignment of the body panel to door surface or the door may inadvertently pop open. Refit the fuel door and fuel door striker. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

Pop Open Condition

1. Open fuel door.
2. Remove plastic door retainer part 1W73-5428608-AA.
3. Modify door retainer as follows:
   a. Clamp retainer in vice.
   b. On the back of the retainer is a locator pin which fits into a hole on the back of the door.
   c. Using a file, remove half of the locator pin which is closest to the slot for the attaching screw.
4. Reinstall modified latch retainer (adjusted to full aft position).

Improper Fit Condition

For vehicles built prior to 10/30/2000 replace fuel door bumper with bumper part N807726-S.

Fuel Door Flushness to Quarter Panel - 3 O'clock Position

1. Open fuel door.
2. Loosen two (2) screws on latch mounting bracket in housing assembly.
3. Reposition latch in/out to correct position.
4. Tighten screws on latch mounting bracket in housing assembly.

Fuel Door Flushness to Quarter Panel - 6 And 12 O'clock Position

1. Open fuel door.
2. Remove screw closest to outboard end of fuel door (i.e., if fuel door is outboard at 6 o'clock position remove lower screw).
3. Insert one (1) 2.0 mm shim part E9SZ-63405A20-A between fuel door hinge and housing assembly.
4. Reinstall screw attaching fuel door to quarter panel.

PART NUMBER	PART NAME
N807726-S	Fuel Door Bumper
E9SZ-63405A20-A	Fuel Door Shim

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
011809AB	Replace Fuel Door Bumper Parts	0.2 Hr.
011809AC	Adjust Fuel Door Three O'Clock Position	0.2 Hr.
011809AD	Adjust Fuel Door Six And Twelve O'Clock Positions	0.2 Hr.
011809A	Remove Fuel Door Retainer Modify And Reinstall (Includes Time To Adjust Retainer)	0.2 Hr.

Copyright © 2001 Ford Motor Company

Article No. 01-18-9 Cont'd.

DEALER CODING

BASIC PART NO.	CONDITION CODE
54405C28	07

OASIS CODES: 111000, 112000