# ELECTRICAL—RADIO—BUZZ, STATIC OR WHINE NOISE HEARD FROM RADIO—VEHICLES PRODUCED BEFORE 5/1/2002 EQUIPPED WITH PIONEER TREMOR RADIO SYSTEM

**Article No. 02-19-5**

**FORD:** 2002 RANGER

## ISSUE

Some vehicles equipped with the Pioneer Tremor radio system, may exhibit a low level whine, buzz or static noise in the speakers, when using the radio or CD. The noise changes with engine RPM and various electrical loads. This may be caused by the speaker wire routing or the radio power/ground system.

## ACTION

To correct the noise, the power/ground and speaker wiring must be rerouted. To accomplish this, some of the wiring in the vehicle harness will be disabled and two overlay harnesses will be installed. Obtain Service repair kit 2L5Z-19B113-AA and follow instructions in kit to repair.

| LABOR OPERATION CLAIMING CHART | | | |
|---|---|---|---|
| **Operation** | **Labor Description** | **Vehicle** | **Time** |
| 021905A | Install Harnesses And Reroute Speaker Wiring | 2002 Ranger Tremor Super Cab - 4dr<br>2002 Ranger Tremor Super Cab - 2dr | 1.2<br>1.4 |

| PART NUMBER | PART NAME |
|---|---|
| 2L5Z-19B113-AA | Radio Wiring Repair Service Kit |

**OTHER APPLICABLE ARTICLES:** NONE
**WARRANTY STATUS:** Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

**DEALER CODING**

| BASIC PART NO. | CONDITION CODE |
|---|---|
| 19A170 | 43 |

**OASIS CODES:** 203000, 203200, 207000

**NOTE:** The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle.

Copyright © 2002 Ford Motor Company