- **DRIVEABILITY—MALFUNCTION INDICATOR LAMP (MIL) ILLUMINATED WITH DIAGNOSTIC TROUBLE CODE (DTC) P1744 WITH NO DRIVEABILITY CONCERNS PRESENT—VEHICLES EQUIPPED WITH 2.0L ZETEC AND F4E-F AUTOMATIC TRANSMISSION PRODUCED BEFORE 9/4/2001**
- **ELECTRICAL—LAMP—MALFUNCTION INDICATOR LAMP (MIL) ILLUMINATED WITH DIAGNOSTIC TROUBLE CODE (DTC) P1744 WITH NO DRIVEABILITY CONCERNS PRESENT—VEHICLES EQUIPPED WITH 2.0L ZETEC AND F4E-F AUTOMATIC TRANSMISSION PRODUCED BEFORE 9/4/2001**

Article No. 01-24-2

FORD: 2001-2002 ESCORT

ISSUE

On some vehicles built prior to 9/4/2001 equipped with the 2.0L Zetec engine and F4E-F Automatic Transmission, diagnosis may be difficult with the Malfunction Indicator Lamp (MIL) illuminated and Diagnostic Trouble Code (DTC) P1744 stored in continuous memory with no driveability concerns present. This may be caused by the calibration of the Powertrain Control Module (PCM).

ACTION

Follow normal diagnostic procedures and verify the condition. If the "no driveability condition" is valid, reprogram the PCM to latest calibration level. Refer to the following PCM Calibration Information Chart.

PCM CALIBRATION INFORMATION

Application	Old Part Number (-12A650-)	Tear Tag	New Part Number (-12A650-)	Old Calibration	New Calibration	NGS/WDS Qualifier
2001 Escort ZX2 Coupe, A/T	1S4F-AUA	JZB0	1S4Z-AUD	1AJ1AZ0500	1AJ1AZ0500	WDS B16.2 Release or Later
2001 Escort ZX2 Coupe, A/T	1S4F-AUB	JZB1	1S4Z-AUD	1AJ1AZ0505	1AJ1AZ0505	WDS B16.2 Release or Later
2001 Escort ZX2 Coupe, A/T	1S4F-AUC	JZB2	1S4Z-AUD	1AJ1AZ0506	1AJ1AZ0506	WDS B16.2 Release or Later
2002 Escort ZX2 Coupe, A/T	1S4F-AUC	JZB2	1S4Z-AUD	1AJ1AZ0506	1AJ1AZ0507	WDS B16.2 Release or Later

Obtain an Authorized Modifications Decal (STAT 5941-2 - obtainable through the PDC) and list the date, dealer number, and summary of modifications performed. Select a prominent place adjacent to the Vehicle Emission Control Information Decal suitable for installing the Authorized Modifications Decal. Clean the area, install the decal, and cover it with a clear plastic decal shield.

Copyright © 2001 Ford Motor Company

AUTHORIZED MODIFICATIONS

THE FOLLOWING MODIFICATIONS HAVE BEEN MADE:
Reprogrammed Powertrain Control Module
(PCM) Per TSB 01-24-2
THESE MODIFICATIONS HAVE BEEN APPROVED, AS APPROPRIATE, BY EPA AND CARB.
DEALER NUMBER: DATE:
CHANGE AUTHORITY:
FPS 8262 9/78 FORD MOTOR COMPANY PRINTED IN U.S.A.

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 504000, 698298