THUMP/BUMP ON ACCELERATION FROM A STOP OR WHEN BRAKING FROM DRIVESHAFT AREA—4X2 AUTOMATIC TRANSMISSION SUPER CAB EDGE MODELS ONLY

Article No. 02-19-1

FORD: 2001-2002 RANGER

Article **02-10-9** is being republished in its entirety to clarify the model line coverage.

ISSUE

Some 4X2 Super Cab Edge model vehicles equipped with an automatic transmission may exhibit a thump or bump sensation felt immediately on acceleration from a stop or upon braking when coming to a complete stop. This is not to be confused with tip-out clunk. This may be caused by the slip-yoke on the driveshaft.

ACTION

Install a new driveshaft which has a revised slip-yoke and lube the driveshaft slip yoke to improve slip characteristics. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

1. Perform diagnostics to insure that condition exists.
2. Inspect the rear axle flange for presence of the yellow dot balance mark.
   - If present, proceed to Step 3
   - If not, perform the following:
     a. Locate yellow dot balance mark on the driveshaft.
     b. Transfer this mark at the same orientation on the pinion flange of the rear axle.
3. To the new driveshaft 1L5Z-4602-XA, apply grease XG-1-C (7-13 grams or .25 to .46 oz.) evenly to the driveshaft slip yoke splines.
4. Remove the old driveshaft from the vehicle.
5. Install the new driveshaft 1L5Z-4602-XA.
6. Align the yellow dot balance mark to the rear axle flange.

CAUTION

IF NEW BOLTS TO RETAIN THE DRIVESHAFT TO THE AXLE ARE NOT AVAILABLE, COAT THE THREADS OF THE ORIGINAL BOLTS WITH THREADLOCK AND SEALER EOAZ-19554-AA OR EQUIVALENT MEETING FORD SPECIFICATION WSK-M2G351-A5.

7. Tighten driveshaft bolts to 65 to 88 Lb-ft (88 to 119 N•m).
8. Check transmission fluid level. Refill if required Mercon V® (XT-5-QM).
9. Verify repair.

CAUTION

USE ONLY MERCON V® TRANSMISSION FLUID. USE OF ANY OTHER FLUID CAN RESULT IN TRANSMISSION FAILURE.

PART NUMBER	PART NAME
XG-1-C	Longlife Grease
1L5Z-4602-XA	Driveshaft
XT-5-QM	Mercon V® Transmission Fluid
EOAZ-19554-AA	Threadlock And Sealer

OTHER APPLICABLE ARTICLES: NONE
SUPERSEDES: 02-10-9
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
021901A	Replace Driveshaft (Includes Time To Verify Condition And Verify Repair	1.1 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
4602	42

OASIS CODES: 597997, 702000, 702200

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle.

Copyright © 2002 Ford Motor Company