ELECTRICAL—FUEL GAUGE—FUEL GAUGE DROPS FROM "FULL" TOO FAST—FUEL GAUGE INDICATES LESS THAN THE ACTUAL FUEL LEFT IN THE TANK—VEHICLES EQUIPPED WITH 2.3L, 3.0L GAS OR 4.0L SOHC ENGINE—VEHICLES PRODUCED BEFORE 3/26/2001 ONLY

Article No. 01-11-2

FORD: 2001 RANGER

This article is being republished in its entirety to update the engine applications.

ISSUE

Some vehicles equipped with a 2.3L, 3.0L gas, or 4.0L SOHC engine built before 3/26/2001 may exhibit a fuel gauge that drops from "FULL" too fast or indicates less than the actual fuel left in the tank (excessive tank reserve). This may be reported by the customer as perceived poor fuel economy or that the fuel tank will not hold the advertised capacity. This may be caused by the accuracy of the sending unit on the fuel pump assembly.

ACTION

Verify condition. Be advised, the fuel tank WILL hold the advertised capacity. If normal diagnostics cannot pinpoint condition, remove the existing fuel pump assembly and replace it with a more accurate fuel pump assembly. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

Verify vehicle exhibits either fuel gauge dropping off from "FULL" quickly, fuel gauge reading inaccurate, excessive fuel consumption, customer assuming fuel tank is wrong size, and/or at "EMPTY" there is excessive amount of fuel within reserve.

If any or all conditions are present and normal diagnostics cannot pinpoint condition, remove existing fuel pump assembly and replace with revised fuel pump assembly. Refer to the parts table in this article for correct listing.

PART NUMBER	PART NAME
1L5Z-9H307-FE	Fuel Pump Assembly - Short Bed Regular Cab With 112″ W/B And Super Cab Models With 126″ W/B
1L5Z-9H307-EE	Fuel Pump Assembly - Regular Cab Long Bed With 118″ W/B

OTHER APPLICABLE ARTICLES: NONE
SUPERSEDES: 01-7-9
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 204000, 204200, 206000, 404000

Copyright © 2001 Ford Motor Company