BODY—CORROSION DAMAGE FROM CHROME LIFTGATE/DECK LID HANDLE APPLIQUE

Article No. 02-25-4

FORD: 2000-2002 FOCUS

ISSUE

Some vehicles may exhibit blisters and/or visual corrosion on the liftgate/deck lid. This may be caused by an interference from the chrome liftgate/deck lid handle applique and sheet metal.

ACTION

Read this TSB in its entirety BEFORE beginning any repairs. Repair as outlined in the service procedures listed below.

SERVICE PROCEDURE

1. Remove the liftgate/deck lid Interior Trim Panel.
2. Remove the liftgate/deck lid handle applique nuts, the license lamp electrical connectors, and then remove the applique, and nameplates.
3. Wipe the liftgate/deck lid repair area with wax and grease remover.
4. Remove all corrosion in the repair area to bare metal using 36 grit sand paper on a 3″ angle grinder. Feather edge all corrosion spots. Blow off the liftgate with compressed air to remove loose dust and debris.
5. Check for an interference fit between the inset in the liftgate/deck lid and the applique. If there is interference, rework the sheet metal as necessary.
6. Wipe the liftgate/deck lid with a wax and grease remover. Wipe dry using a clean, lint-free cloth to remove all residue. Keep wiping until the surface is completely dry.
7. Mask the liftgate/deck lid as necessary.
8. Mix and apply Ford Approved self-etching primer to the liftgate/deck lid and let flash per manufacturer's label recommendations.
9. Mix and apply (1.5 mils min.) primer surfacer following the manufacturer's label recommendations and bake at 140° F panel temperature per manufacturer's recommended baking time.
10. Sand the repair area with 400 - 600 grit sandpaper. Scuff the entire liftgate/deck lid with a red Scotchbrite for future clear coat application.
11. Blow off the area with compressed air to remove loose dust and debris.
12. Wipe the liftgate/deck lid with a wax and grease remover. Wipe dry using a clean, lint-free cloth to remove all residue.

NOTE

KEEP WIPING UNTIL THE SURFACE IS COMPLETELY DRY. ANY RESIDUE MAY RESULT IN CONTAMINATION OF THE COATINGS TO BE APPLIED FOLLOWING THIS STEP.

13. Mix and apply Ford Approved base coat material to point of hiding the repair area, following the manufacturer's label recommendations and flash time.
14. Mix and apply (2.0 mils) Ford Approved Clear coat to the entire panel. Let flash, booth purge, and bake at 140° F panel temperature following manufacturer's recommended baking time.
15. Demask the liftgate/deck lid.
16. Reinstall nameplates.
17. Remove the license plate lamp assemblies from the old liftgate/deck lid handle applique and install into a new liftgate/deck lid handle applique (YS4Z-54430A70-BAA for Sedan, 3S4Z-74430A70-AAG for Wagon), install the applique onto the liftgate/deck lid, torque the fasteners to 28 ± 4 Lb-in. (3.2 ± .05 N•m), reinstall electrical connectors and trim panel.

PART NUMBER	PART NAME
YS4Z-54430A70-BAA	Liftgate/Deck Lid Handle Applique - Sedan
3S4Z-74430A70-AAG	Liftgate/Deck Lid Handle Applique - Wagon

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle.

Copyright © 2002 Ford Motor Company

Article No. 02-25-4 Cont'd.

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
022504A	Replace Liftgate/Deck Lid Handle Applique Only. For The Refinish And Paint Repair Section Of This TSB, Refer To Normal Paint Labor Operations	0.3 Hr.

DEALER CODING

BASIC PART NO.	CONDITION CODE
430A70	14

OASIS CODES: 106000, 108000, 111000