• **ELECTRICAL—LAMP—LOW COOLANT WARNING INDICATOR LAMP ILLUMINATED—VEHICLES EQUIPPED WITH 3.0L DURATEC ENGINE ONLY** • **COOLING SYSTEM—LOW COOLANT WARNING INDICATOR LAMP ILLUMINATED—VEHICLES EQUIPPED WITH 3.0L DURATEC ENGINE ONLY**	**Article No. 01-13-1**

FORD: 2001 ESCAPE

ISSUE

Some vehicles equipped with the 3.0L Duratec engine may exhibit a false low coolant warning indicator lamp illuminating intermittently. This may be caused by the coolant sensor float sinking in the coolant recovery (degas) tank. This may occur when coolant in the reservoir is at the full mark.

ACTION

Replace the coolant recovery (degas) tank equipped with a revised float and sender 1L8Z-8A080-BB.

Refer to the 2001 Escape Workshop Manual Section 303-03 Engine Cooling, for replacement procedures.

PART NUMBER	PART NAME
1L8Z-8A080-BB	Coolant Recovery (Degas) Tank

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 204000, 206000, 402000, 497000

Copyright © 2001 Ford Motor Company