CALIBRATION—RECALIBRATION OF POWERTRAIN CONTROL MODULES (PCMS) AFTER REPLACEMENT—SERVICE TIP—ALTERNATE FUEL VEHICLES ONLY	Article No. 00-6-11

FORD: 1996-2000 CONTOUR
1996-1999 ECONOLINE
1996-2000 F-150, F-250
2000 SUPER DUTY F SERIES

ISSUE

Some bi-fuel vehicles may require Powertrain Control Module (PCM) replacement during service and may not run on CNG or LPG. The reason may be that the bi-fuel calibration was not flashed into the PCM.

ACTION

If the PCM is replaced for any reason on these vehicles, the PCM must be reprogrammed to the bi-fuel calibration. The PCM that is ordered is programmed for base gasoline vehicle operation only. The bi-fuel calibrations may be accessed through the FORDSTAR network and on the regular WDS/NGS-SBTS system CD. The new PCM must be reprogrammed with the correct bi-fuel calibration using the reprogramming service procedure. Failure to reprogram the PCM to a bi-fuel calibration will make bi-fuel operation impossible. Retest vehicle operation, road test for drive concerns in both bi-fuel and gasoline modes, and test for AFCM and Malfunction Indicator (MIL) codes.

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 601300, 602300, 607400, 607500, 608400, 608500, 609400, 609500, 610500, 611500, 612500, 612600, 613400, 613500, 614500, 614600, 615500, 617400, 618400, 619400, 623000, 690000, 698298