TRANSMISSION—4R70W—HARSH 1-2 SHIFT—VEHICLES EQUIPPED WITH 4.2L ENGINE AND 3.31 OR 3.55 AXLE RATIO—VEHICLES PRODUCED 8/2/1999 THROUGH 8/4/2000 ONLY

Article No. 01-20-8

FORD: 2000 F-150

ISSUE

Some vehicles equipped with the 4.2L engine, 4R70W transmission and 3.31 or 3.55 axle ratio may exhibit an intermittent harsh 1-2 shift during light throttle or parking lot maneuvers. This may be caused by the calibration of the Powertrain Control Module (PCM).

ACTION

Verify condition. If normal diagnostics cannot pinpoint the condition, reprogram the PCM to the latest level calibration. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

Follow normal diagnostic procedures and verify the condition.

1. If the condition is valid, first service all Diagnostic Trouble Codes (DTC's) that may be present.
2. Determine if the condition is caused by a internal transmission component and repair as required.
3. Clear all DTC's and validate the repair.
4. Reprogram the PCM as necessary. Refer to the following PCM calibration chart.
5. Follow the procedures found in the Powertrain Control/ Emission Diagnosis (PC/ED) Workshop Manual to reprogram the PCM.

PCM CALIBRATION INFORMATION

Application	Old Part Number (-12A650-)	Tear Tag	New Part Number (-12A650-)	Old Calibration	New Calibration	NGS/WDS Qualifier
4.2L F-150, 4R70W	YL3F-AC	FPQ3	YU7Z-EAA	0F512A0A06	0F512A0A06	WDS B15.1 Release or Later
4.2L F-150, 4R70W	YL3P-BC	UUV3	YU7Z-EBA	0F512B0A06	0F512B0A06	WDS B15.1 Release or Later
4.2L F-150, 4R70W	YL3F-CC	NBW3	YU7Z-ECA	0F512C0B06	0F512C0B06	WDS B15.1 Release or Later
4.2L F-150, 4R70W	YL3F-DC	ZAC3	YU7Z-EDA	0F512D0B06	0F512D0B06	WDS B15.1 Release or Later

Obtain an Authorized Modifications Decal (STAT 5941-2 - obtainable through the PDC) and list the date, dealer number, and summary of modifications performed. Select a prominent place adjacent to the Vehicle Emission Control Information Decal suitable for installing the Authorized Modifications Decal. Clean the area, install the decal, and cover it with a clear plastic decal shield.

Copyright © 2001 Ford Motor Company

AUTHORIZED MODIFICATIONS

THE FOLLOWING MODIFICATIONS HAVE BEEN MADE:
Reprogrammed Powertrain Control Module
(PCM) Per TSB 01-20-8
THESE MODIFICATIONS HAVE BEEN APPROVED, AS APPROPRIATE, BY EPA AND CARB.
DEALER NUMBER: DATE:
CHANGE AUTHORITY:
FPS 8262 9/78 FORD MOTOR COMPANY PRINTED IN U.S.A.

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 501000