Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

September 2000

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Owner Notification Program 00B55: Certain 2000 Taurus and Sable Vehicles Equipped with 3.0L Engines – Engine Performance

OASIS : Yes
OWNER LIST: Yes
PARTS RETURN: No
PROGRAM TERMS: This program will be in effect until October 31, 2001, regardless of mileage.

AFFECTED VEHICLES

Certain 2000 model year Taurus and Sable vehicles equipped with 3.0L engines built at the Atlanta Assembly Plant from May 6, 1999 through June 28, 2000, and built at the Chicago Assembly Plant from August 12, 1999 through June 30, 2000.

REASON FOR PROGRAM

Prior to July 27, 2000, calibrations released to re-program the Powertrain Control Module (PCM) on 2000 model year Taurus and Sable vehicles may result in performance or driveability degradation.

These calibrations would have caused dealers to inadvertently trigger an "Export Octane Adjust" feature in the engine control strategy, resulting in a "retard spark timing condition", which is known to adversely affect engine performance.

SERVICE ACTION

Revised calibrations are now available, and dealers must reprogram the vehicle's PCM using one of the methods outlined in Attachment III of this owner notification.

Note: Reprogramming the PCM using program code 00B55 is the only authorized service chargeable to this program. This service involves the reprogramming of the Powertrain Control Module (PCM) without diagnosis. Any diagnostic trouble codes (DTCs) must be diagnosed before reprogramming the PCM and are **not** chargeable to this program. Claims will be audited to verify that this direction is being followed.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter

QUESTIONS?

Claims Information:	1-800-423-8851
Other Program Questions:	1-800-325-5621

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

Owner Notification Program 00B55
Certain 2000 Taurus and Sable vehicles equipped with 3.0L engines
Engine Performance

OASIS

You must use OASIS to determine if a vehicle is eligible for this Program.

PLEASE NOTE

Correct all vehicles in stock before delivery.

DEALER-OWNER CONTACT

Promptly correct all affected vehicles on the enclosed list and other eligible vehicles which are brought to your dealership.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Ford Motor Company will refund only those owner-paid repairs made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer).

Program Code:	00B55
Misc. Expense:	REFUND
Misc. Expense:	ADMIN
Misc. Expense:	0.2 Hr.

Refer to ACESII manual for refund information.

RENTAL CARS

Rental cars are not approved for this program.

Owner Notification Program 00B55
Certain 2000 Taurus and Sable vehicles equipped with 3.0L engines
Engine Performance

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Reprogram Powertrain Control Module and Affix Modification Label	00B55B	0.4 Hours

PARTS REQUIREMENTS

Parts Ordering Information

Parts will not be direct shipped for this Program. Order your parts requirement through normal order processing channels.

Part Number	Description	Quantity
FPS-8262	Authorized Modifications Label (Free to Dealers)	1

EXCESS STOCK RETURN

Does not apply.

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121
1-800-392-3673
www.ownerconnection.com

October 2000

00B55

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

Our records indicate that you brought your vehicle to the dealership to be serviced under Owner Notification Program 00B38, or you returned to the dealership under normal vehicle warranty for driveability/performance concerns. This service would have resulted in your Powertrain Control Module being re-programmed.

We have discovered that calibrations previously released to re-program the Powertrain Control Module (PCM) of your vehicle may result in performance or driveability degradation.

We wish to apologize for this and advise you that the calibration concerns have been corrected and that Ford Motor Company is providing a no-charge service, Program Number 00B55, to resolve this engine performance concern on your vehicle.

You have until October 31, 2001, to take advantage of this program, regardless of mileage.

Please call your dealer without delay. Provide the Vehicle Identification Number (located at the beginning of this letter), and ask for a service date for Owner Notification Program 00B55. The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time.

As previously stated, your dealer, free of charge to you, will perform this repair to your vehicle. To aid in this process it would be helpful if when you bring your vehicle in for this service you show the dealer this letter. However, if you misplace this letter, your dealer will still do the work, free of charge. If you've changed address or sold the vehicle, please fill out the enclosed prepaid postcard and mail it to us.

We are sorry for the inconvenience this error has caused you, and as a small token of our appreciation for your patience we are enclosing a 'Mag Lite' Flashlight.

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs