NEW CALIBRATION SOFTWARE—SERVICE TIP—ELECTRIC VEHICLES ONLY	Article No. 00-10-8

FORD: 1998-2000 RANGER

ISSUE

A New Generation Star (NGS) software update card was recently sent to all Electric Vehicle (EV) dealerships.

ACTION

Refer to the following text to view the software content.

SERVICE PROCEDURE

XL5F-10B687-BH (Version 3.3.1) Pb-Acid BCM - To be used on Pb-Acid ONLY (refer to ONP 00B37)

NOTE
VERIFY SOFTWARE LEVEL (USING NGS) OF BCM BEFORE UPDATING.

CAUTION
DO NOT UPDATE NIMH VEHICLES WITH XL5F-10B687-BH (VERSION 3.3.1) PB-ACID BCM SOFTWARE. FAILURE TO FOLLOW THIS CAUTION MAY RESULT IN THE REPLACEMENT OF THE BCM. THE PB-ACID ELECTRIC RANGERS THAT ARRIVE AT THE DEALERSHIP FOR SERVICE ARE TO BE UPDATED WITH THE XL5F-10B687-BH (VERSION 3.3.1) BCM SOFTWARE (UNLESS THE BCM IS ALREADY AT THIS LEVEL). IF THE MODEL YEAR IS 1998 AND THE BCM SOFTWARE LEVEL IS F8YF-10B687, REPLACE THE BCM (REFER TO RECALL/ONP 99B17) BEFORE PERFORMING THE UPDATE. CHECK THE BCM SOFTWARE LEVEL (USING MODULE IDENTIFICATION UNDER THE BCM MENU ON THE NGS TESTER) BEFORE UPDATING THE VEHICLE.

YL5F-14B298-AA (Version 15.0) TIM Software

This software will allow for the following vehicle performance characteristics:

- At high State of Charge (SOC), the vehicle will perform regenerative braking when driving downhill.
- Up to 10% increase in range while driving in E (Economy Mode).

Some customers may recognize a slight reduction in acceleration in this mode. The Electric Rangers that arrive at the dealership for service are to be updated with the YL5F-14B298-AA (Version 15.0) TIM software (unless the TIM is already at this level). Check the TIM software level (using module identification under the TIM menu on the NGS Tester) before updating the vehicle. Refer to TSB 00-7-6.

XL5F-10B687-AH (Version 7.1) NiMH BCM Software

This software will:

- Improve the linearity of the State of Charge (SOC) and Distance-to-Empty (DTE) gauges.
- Increase the driver's perception of vehicle range.

NOTE
VERIFY SOFTWARE LEVEL (USING NGS) OF BCM BEFORE FLASHING.

CAUTION
DO NOT UPDATE PB-ACID VEHICLES WITH XL5F-10B687-AH (VERSION 7.1) NIMH BCM SOFTWARE. FAILURE TO FOLLOW THIS CAUTION MAY RESULT IN THE REPLACEMENT OF THE BCM. THE NIMH ELECTRIC RANGERS THAT ARRIVE AT THE DEALERSHIP FOR SERVICE ARE TO BE UPDATED WITH THE XL5F-10B687-AH (VERSION 7.1) BCM SOFTWARE (UNLESS THE BCM IS ALREADY AT THIS LEVEL). CHECK THE BCM SOFTWARE LEVEL (USING MODULE IDENTIFICATION UNDER THE BCM MENU ON THE NGS TESTER) BEFORE UPDATING THE VEHICLE.

OTHER APPLICABLE ARTICLES: 00-7-6
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 204000, 607500, 622000