Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
48121
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan

March 2002

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Safety Recall 02S33: Certain 2000 through 2001 Model Year Windstar Vehicles Electrical Connector/Sealer Skip

AFFECTED VEHICLES

Certain 2000 through 2001 model year Windstar vehicles built at the Oakville Assembly Plant from Job #1, 2000 through September 28, 2001.

SAFETY CONCERN

In some of the affected vehicles, water and other contaminants (dirt, salt, etc.) may enter into the right rear passenger compartment due to a missing body sealer condition – occurring during the assembly process. If water or other contaminants enter this area, there is potential for a short circuit in the electrical connector located at the rear wire harness. A short circuit can lead to malfunctions of the rear lighting system, reverse park-aid system, or trailer tow electrical system. A sustained short circuit can result in melted connectors, and potentially lead to fire.

SERVICE ACTION

The dealer must inspect the affected vehicles for signs of corrosion, or wire damage, and repair as instructed in the Technical Instructions (Attachment III). This must be done on all of the affected vehicles in your inventory, as well as vehicles that have been delivered to customers.

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to $5,000 per vehicle.

© Copyright 2002 Ford Motor Company

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Attachment IV: Material Safety Data Sheet (MSDS)
Customer Notification Letter(s)

QUESTIONS?

Claims Information:……..……....1-800-423-8851
Other (Dealer Only) Recall Questions:……..……...1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2002 Ford Motor Company

Safety Recall 02S33
Certain 2000 through 2001 Model Year Windstar Vehicles
Electrical Connector/Sealer Skip

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

PROMPTLY CORRECT

Promptly correct all affected vehicles on your dealer Online Involved Unit Listing available on QCDealer.com. Also, correct other affected vehicles identified in OASIS which are brought to your dealership.

DEALER-OWNER CONTACT

Immediately contact any of your affected owners whose names are not on your VIN list but identified in OASIS. Give the owner a copy of the Owner Letter and schedule a service date.

Note: These dealer listings may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than in connection with this recall is a violation of law in several states/provinces/countries. Accordingly, you must limit the use of this listing to the follow-up necessary to complete this action.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs applicable to this recall, which were made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer). Refer to ACESII manual for refund information.

RENTAL

The use of rental vehicles is not authorized for this program.

© Copyright 2002 Ford Motor Company

Safety Recall 02S33
Certain 2000 through 2001 Model Year Windstar Vehicles
Electrical Connector/Sealer Skip

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Inspect for corrosion/damage and Install Butyl Patch and Sealer	02S33B	0.7 Hours
Inspect for corrosion/damage, Repair Connector, w/o Trailer Tow/Reverse Aid and Install Butyl Patch and Sealer	02S33C	1.2 Hours
Inspect for corrosion/damage, Repair Connector, w/Trailer Tow/Reverse Aid and Install Butyl Patch and Sealer	02S33D	1.5 Hours
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS

Parts will be direct shipped to dealers by stock order for this recall. Dealers should receive their individual seed stock allocation by March 30. Each dealer will receive between 1-20 kits based on the size of the dealership. Do not order parts until you have received your seed stock and are in need of additional kits. Parts will not be stocked in the PDCs as they are direct shipped from the supplier.

Ordering procedure noted below:

Stock Orders	10 days after launch	Call 1-800-325-5621
Stock Orders	After April 1	Normal order process
Interim Orders	10 days after launch	Call 1-800-325-5621
Interim Orders	After April 1	Normal order process

Emergency Orders will be restricted except for the most severe cases. To order emergency parts, call 1-800-325-5621. You will be required to give the VIN number of the vehicle involved.

Note: Because this program will involve a seed stock allocation for each dealer involved, you will not be able to place orders for parts until after April 1. The seed stock process will take place from launch through March 30, 2002. During this time period, dealers can call the support center if there is an urgent need for parts.

Part Number	Description	Quantity
2F2Z-114B34-AA	Electrical Connector/Sealer Kit	**1 kit repairs 5 vehicles**

© Copyright 2002 Ford Motor Company

Safety Recall 02S33
Certain 2000 through 2001 Model Year Windstar Vehicles
Electrical Connector/Sealer Skip

PARTS REQUIREMENTS

WARNING – DO NOT OVER-ORDER MATERIAL
1 KIT WILL REPAIR 5 VEHICLES
5 KITS WILL REPAIR 25 VEHICLES
10 KITS WILL REPAIR 50 VEHICLES

This kit contains a special adhesive. Please print Attachment IV of this bulletin, that contains the MSDS (Material Safety Data Sheet), for your records.

Note: This adhesive is time-sensitive. The average shelf-life is 9 months. Please rotate stock accordingly.

ORDER INFORMATION

The DOR/COR for this program is 50247. This number identifies parts ordered for this recall through the Special Service Support Center (1-800-325-5621).

PARTS RETENTION

Follow the provisions of the Warranty and Policy Manual for “Parts Retention and Return Procedures”.

DEALER PRICE

For latest prices, refer to DOES II or updated price book.

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

© Copyright 2002 Ford Motor Company

LORD

MATERIAL SAFETY DATA SHEET

SECTION 1 - CHEMICAL PRODUCT AND COMPANY IDENTIFICATION

Product Name: **FUSOR MATCH SEALER/ADHESIVE**

Product Use/Class: **URETHANE SEALER/ADHESIVE**

Reference: Applies to Stock Number 800, 801

LORD CORPORATION
CHEMICAL PRODUCTS DIVISION
2000 WEST GRANDVIEW BLVD
ERIE, PA 16514

INFORMATION TELEPHONE: 814 868-3611

TRANSPORTATION EMERGENCY
CALL CHEMTREC: 800 424-9300

NON-TRANSPORTATION EMERGENCY: 814 763-2345

EFFECTIVE DATE: 09/30/1999

SUPERCEDES DATE: 09/16/1999

SECTION 2 - COMPOSITION/INFORMATION ON INGREDIENTS

Chemical Name	CAS Number	Weight % Less Than	ACGIH TLV-TWA	ACGIH TLV-STEL	OSHA PEL-TWA	OSHA PEL-CEILING	Units	Skin
Xylene	1330-20-7	10 %	100	150	100	N.E.	ppm	
Diphenylmethane diisocyanate	26447-40-5	1.0 %	.005	N.E.	N.E.	0.02	ppm	

N.E. - Not Established, S - Skin Designation, C - Ceiling

SECTION 3 - HAZARDS IDENTIFICATION

***** EMERGENCY OVERVIEW ***:** Buff colored Paste, with Mild odor. Combustible liquid and vapor. May cause allergic skin reaction. May cause allergic respiratory reaction. Vapor harmful; may affect the brain or nervous system causing dizziness, headache or nausea. Causes skin and eye irritation. Causes respiratory tract irritation.

EFFECTS OF OVEREXPOSURE - EYE CONTACT: Causes eye irritation.

EFFECTS OF OVEREXPOSURE - SKIN CONTACT: May cause skin sensitization. May cause dermatitis. Causes skin irritation.

EFFECTS OF OVEREXPOSURE - INHALATION: Possible irritation of the respiratory system can occur causing a variety of symptoms such as dryness of the throat, tightness of the chest, and shortness of breath. Allergic conditions can occur in certain individuals with high sensitivity to isocyanates; this may result in asthma-like symptoms. May cause central nervous system depression characterized by the following progressive steps: headache, dizziness, staggering gait, confusion, unconsciousness or coma. May cause respiratory sensitization. May cause lung damage.

EFFECTS OF OVEREXPOSURE - INGESTION: Harmful if swallowed. Ingestion is not an expected route of entry in industrial or commercial uses.

EFFECTS OF OVEREXPOSURE - CHRONIC HAZARDS: May cause liver or kidney damage. Repeated or prolonged solvent overexposure may result in permanent central nervous system damage. May cause long-term lung damage. May affect the gastrointestinal system. May affect the blood and blood-forming organs. Chronic skin contact may cause dermatitis.

PRIMARY ROUTE(S) OF ENTRY: Skin Contact, Inhalation, Ingestion, Eye Contact

SECTION 4 - FIRST AID MEASURES

FIRST AID- EYE CONTACT: Flush eyes immediately with large amount of water for at least 15 minutes holding eyelids open while flushing. Get prompt medical attention.

FIRST AID - SKIN CONTACT: Flush contaminated skin with large amounts of water while removing contaminated clothing. Wash affected skin areas with soap and water. Get medical attention if symptoms occur.

FIRST AID - INHALATION: Move person to fresh air. Restore and support continued breathing. If breathing is difficult, give oxygen. Get immediate medical attention.

FIRST AID - INGESTION: If swallowed, do not induce vomiting. Give victim one or two glasses of water or milk. Call a physician or poison control center immediately for further instructions. Never give anything by mouth to an unconscious person.

SECTION 5 - FIRE FIGHTING MEASURES

FLASH POINT: 132F, 56C
(Setaflash Closed Cup)

LOWER EXPLOSIVE LIMIT (%): 1.00
UPPER EXPLOSIVE LIMIT (%): 7.00

AUTOIGNITION TEMPERATURE: N.D.

OSHA FLAMMABILITY CLASSIFICATION: COMBUSTIBLE LIQUID - CLASS II

EXTINGUISHING MEDIA: Carbon Dioxide, Dry Chemical, Foam, Water Fog

UNUSUAL FIRE AND EXPLOSION HAZARDS: Combustible liquid and vapor. Keep containers tightly closed. Isolate from heat, electrical equipment, sparks, open flame, and other sources of ignition. Closed containers may rupture when exposed to extreme heat. Use water spray to keep fire exposed containers cool.

SPECIAL FIREFIGHTING PROCEDURES: Wear full firefighting protective clothing, including self-contained breathing apparatus (SCBA). Water spray may be ineffective. If water is used, fog nozzles are preferable. During a fire, irritating and/or toxic gases and particulate may be generated by thermal decomposition or combustion.

SECTION 6 - ACCIDENTAL RELEASE MEASURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: Keep non-essential personnel a safe distance away from the spill area. Remove all sources of ignition (flame, hot surfaces, and electrical, static or frictional sparks). Avoid breathing vapors. Use self-contained breathing equipment. Notify appropriate authorities if necessary. Contain and remove with inert absorbent material. Avoid contact. Before attempting cleanup, refer to hazard caution information in other sections of the MSDS form.

SECTION 7 - HANDLING AND STORAGE

HANDLING: Keep closure tight and container upright to prevent leakage. Avoid skin and eye contact. Wash thoroughly after handling. Avoid breathing of vapor or spray mists. Do not handle until all safety precautions have been read and understood. Empty containers should not be re-used. Use with adequate ventilation. Because empty containers may retain product residue and flammable vapors, keep away from heat, sparks and flame; do not cut, puncture or weld on or near the empty container. Do not smoke where this product is used or stored.

STORAGE: Do not store or use near heat, sparks, or open flame. Refer to OSHA 29CFR Part 1910.106 "Flammable and Combustible Liquids" for specific storage requirements. Store only in well-ventilated areas. Do not puncture, drag, or slide container. Keep container closed when not in use.

SECTION 8 - EXPOSURE CONTROLS/PERSONAL PROTECTION

ENGINEERING CONTROLS: Sufficient ventilation in pattern and volume should be provided in order to maintain air contaminant levels below recommended exposure limits. Caution: Solvent vapors are heavier than air and collect in lower levels of the work area.

RESPIRATORY PROTECTION: This product contains isocyanates which have poor odor warning properties. If occupational exposure limits are exceeded, a NIOSH/MSHA approved supplied-air respirator is required. Observe OSHA regulations (29CFR 1910.134) for respirator use.

SKIN PROTECTION: Use neoprene, nitrile, or rubber gloves to prevent skin contact.

EYE PROTECTION: Use safety eyewear including safety glasses with side shields and chemical goggles where splashing may occur.

OTHER PROTECTIVE EQUIPMENT: Use disposable or impervious clothing if work clothing contamination is likely. Remove and wash contaminated clothing before reuse.

HYGIENIC PRACTICES: Wash hands before eating, smoking, or using toilet facility. Do not smoke in any chemical handling or storage area. Food or beverages should not be consumed anywhere this product is handled or stored. Wash thoroughly after handling.

SECTION 9 - PHYSICAL AND CHEMICAL PROPERTIES

BOILING RANGE:	282 - 282 F	**VAPOR DENSITY:**	Heavier than Air
APPEARANCE:	Buff colored	**EVAPORATION RATE:**	Slower than Ether
PHYSICAL STATE:	Paste	**DENSITY, LB/GL:**	10.08
ODOR:	Mild	**SPECIFIC GRAVITY:**	1.21
SOLUBILITY IN H2O:	Insoluble	**pH:**	N.A.
FREEZE POINT:	N.D.	**ODOR THRESHOLD:**	N.D.
VOLATILE BY WEIGHT:	5.9%	**VOLATILE BY VOLUME:**	8.2%
VAPOR PRESSURE:	N.D.		
COEFFICIENT OF WATER/OIL DISTRIBUTION:	N.D.		

(See section 16 for abbreviation legend)

SECTION 10 - STABILITY AND REACTIVITY

CONDITIONS TO AVOID: High temperatures. Sources of ignition.

INCOMPATIBILITY: Amines, acids, water, hydroxyl, or active hydrogen compounds.

HAZARDOUS DECOMPOSITION PRODUCTS: Monomeric isocyanate, traces of hydrogen cyanide, nitrogen dioxide. Carbon monoxide, carbon dioxide.

HAZARDOUS POLYMERIZATION: Hazardous polymerization will not occur under normal conditions.

STABILITY: Product is stable under normal storage conditions.

SECTION 11 - TOXICOLOGICAL INFORMATION

PRODUCT LD50	**(ORAL)**	**:** No Data
	(DERMAL)	**:** No Data
PRODUCT LC50		**:** No Data

SECTION 12 - ECOLOGICAL INFORMATION

ECOLOGICAL INFORMATION: No Information.

SECTION 13 -DISPOSAL CONSIDERATIONS

DISPOSAL METHOD: Disposal should be done in accordance with Federal (40CFR Part 261), state and local environmental control regulations. If waste is determined to be hazardous, use licensed hazardous waste transporter and disposal facility.

SECTION 14 - TRANSPORTATION INFORMATION

DOT PROPER SHIPPING NAME: ADHESIVE
DOT HAZARD CLASS: 3
DOT UN/NA NUMBER: UN1133
PACKING GROUP: III
EMERGENCY RESPONSE GUIDE NUMBER: 127

SECTION 15 - REGULATORY INFORMATION

U.S. FEDERAL REGULATIONS: AS FOLLOWS -

OSHA: HAZARDOUS BY DEFINITION OF HAZARD COMMUNICATION STANDARD (29 CFR 1910.1200)

SARA SECTION 313:
This product contains the following substances subject to the reporting requirements of Section 313 of Title III of the Superfund Amendment and Reauthorization Act of 1986 and 40 CFR part 372:

CHEMICAL NAME	CAS NUMBER	WT % IS LESS THAN
Xylene	1330-20-7	10 %

TOXIC SUBSTANCES CONTROL ACT:

INVENTORY STATUS
The chemical substances in this product are on the TSCA Section 8 Inventory.

EXPORT NOTIFICATION
This product contains the following chemical substances subject to the reporting requirements of TSCA 12(B) if exported from the United States:

NONE

INTERNATIONAL REGULATIONS: AS FOLLOWS -

CANADIAN WHMIS: This MSDS has been prepared in compliance with Controlled Product Regulations except for the use of the 16 headings.

CANADIAN WHMIS CLASS: B3

SECTION 16 - OTHER INFORMATION

HMIS RATINGS - HEALTH: 2* FLAMMABILITY: 2 REACTIVITY: 1

* - Indicates a chronic hazard; see Section 3

REASON FOR REVISION: Computer System Upgrade

VOLATILE ORGANIC COMPOUNDS (Calculated) : 0.61 lbs/gal, 73 grams/ltr

LEGEND: N.A. - Not Applicable, N.E. - Not Established, N.D. - Not Determined

990376070R

DISCLAIMER

The information contained herein is, to the best of our knowledge and belief, accurate. However, since the conditions of handling and use are beyond our control, we make no guarantee of results, and assume no liability for damages incurred by use of this material. It is the responsibility of the user to comply with all applicable federal, state and local laws and regulations.

Ford Motor Company

A. R. O'Neill
Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

April 2002

Safety Recall 02S33

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in certain 2000 through 2001 Model Year Windstar vehicles.

We apologize for this situation and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with Ford and Lincoln Mercury dealers, is to provide you with the highest level of service and support possible.

What the issue is …

In some of the affected vehicles, water and other contaminants (dirt, salt, etc.) may enter into the right rear passenger compartment due to a missing body sealer condition – occurring during the assembly process. If water or other contaminants enter this area, there is potential for a short circuit in the electrical connector located at the rear wire harness. A short circuit can lead to malfunctions of the rear lighting system, reverse park-aid system, or trailer tow electrical system. A sustained short circuit can result in melted connectors, and potentially lead to fire.

What Ford Motor Company and your dealer will do ...

Ford Motor Company will inspect the area of concern on your vehicle. If no corrosion or damage to the area is found, a protective seal will be added to the area. If damage or corrosion is found, your vehicle will be repaired free of charge (parts and labor).

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling requirements, your dealer may need your vehicle for a longer period of time.

What we are asking you to do …

Call your dealer without delay. If you do not already have a servicing dealer, please access www.dealerconnection.com for dealer addresses, maps, and driving instructions. Ask for a service date and whether parts are in stock for Safety Recall 02S33. If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week after ordering.

© Copyright 2002 Ford Motor Company

When you bring your vehicle in, show the dealer this letter. However, If you misplace this letter, your dealer will still do the work, free of charge.

If you have already paid for this service …

If you paid to have this service done before the date of this letter, Ford is offering a refund. To receive the refund, please give your paid original receipt to your dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you have changed address or sold the vehicle …

Please fill out the enclosed prepaid postcard and mail it to us so we can update our records. If you have sold the vehicle, the information you provide on the postcard will be used to notify the new owner about this safety recall.

If you have concerns …

If you have trouble getting your vehicle repaired promptly and without charge, please contact your dealership's Service Manager for assistance. If you still have concerns, please contact the Ford Motor Company Customer Relationship Center and one of our representatives will be happy to assist you:

Call (866) 436-7332

Office Hours (Eastern Time Zone)
Monday through Friday: 8AM – 11PM
Saturday: 8AM – 6PM

Hearing-impaired call (800) 232-5952 TDD for the hearing impaired.

Or you may contact us through the Internet …

www.ownerconnection.com

If you are still having trouble getting your vehicle repaired and without charge, you may write the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline at 1-888-327-4236 or 1-800-424-9393.

Quality Care service is there for you all year long.



Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company providing automotive products and services. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2002 Ford Motor Company