Related Newsletter Articles

01B85 Focus Rear Wheel Bearings

12/17/2001

Supplement 1 was issued on December 10th. It is **imperative** that every Dealer review the updates prior to performing this program.

Spindles will rarely be required. If the double-lip water seal becomes deformed during installation, please replace the seal only with part # 1M5Z-1175-AA. Seal damage does **not** require spindle replacement.

Important: The spindle is manufactured without a chamfer on the leading edge of the seal land, thus leaving a square, sharp corner. This corner (and any burrs or corrosion) must be removed using the supplied emery cloth, prior to seal installation, or damage to the double-lip seal will result.

Please be aware that the disk brake kit (1M5Z-4A013-LD) listed in the bulletin includes the spindle and seal. The Non-ABS (1M5Z-4A013-V V) and ABS drum kits (1M5Z-4A013-W W) do not include a spindle.

There are approximately 1500 vehicle's that require the disk brake kit (1M5Z-4A013-LD). To order, you must call the Special Service Support Center (1-800-325-5621).

Again, if the procedure is followed, spindles will rarely be required. If a spindle replacement is required for the non-ABS and ABS drum kits, order the appropriate spindle shown below:

ABS Drum, Spindle with Seal	1M5Z-4A013-AA
Non-ABS, Spindle with Seal	1M5Z-4A013-BA

Copyright © 2001 Ford Motor Company
Published By: **Recall/Service Programs Department**
Ford Customer Service Division