• **CLIMATE CONTROL—LOUD A/C CLUTCH CYCLING NOISE—VEHICLES EQUIPPED WITH 4.0L OHV ENGINE ONLY** • **NOISE—LOUD A/C CLUTCH CYCLING NOISE—VEHICLES EQUIPPED WITH 4.0L OHV ENGINE ONLY**	**Article No. 01-21-2**

FORD: 1993-2000 RANGER

This article is being republished in its entirety to update the Service Procedure and to clarify the parts involved.

ISSUE

Some vehicles equipped with 4.0L OHV engines may exhibit a loud A/C clutch engagement. Using a different design A/C clutch hub/disc assembly may reduce this A/C clutch engagement noise.

ACTION

Replace the current designed leaf spring style A/C clutch hub/disc assembly with the 3-eye style clutch hub/disc, part number F3DZ-19D786-A, and adjust the A/C clutch air gap to 0.35-0.85mm (0.014-0.033 in). Refer to the appropriate Workshop Manual for removal and installation procedures.

PART NUMBER	PART NAME
F3DZ-19D786-A	A/C Clutch Disc And Hub Assembly

OTHER APPLICABLE ARTICLES: NONE
SUPERSEDES: 01-18-6
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 208000, 208999, 702000, 702100

Copyright © 2001 Ford Motor Company