Ford Motor Company

Service Recall Bulletin

July 2000

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: **Safety Recall 00S11:** Certain 2000 Model Year Windstars – Fuel Line Retention.

AFFECTED VEHICLES

Certain 2000 model year Windstar vehicles built at the Oakville Assembly Plant from April 19, 2000 through April 26, 2000.

SAFETY CONCERN

Some of the affected vehicles may have stainless steel under body fuel supply and return line end-forms not built to drawing tolerances. This could result in lower than intended pull-off forces for the joint.

The vehicles still meet all crash requirements and there is no effect on normal vehicle operation. However, a quick connect joint with reduced pull-off load could potentially separate and leak fuel during a very severe vehicle collision.

SERVICE ACTION

The dealer must install a retaining clip over the quick connect joint of the fuel supply and return lines. This must be done on all of the affected vehicles.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information

QUESTIONS?

Claims Information:……...1-800-423-8851
Other (Dealer Only) Recall Questions:……...1-800-325-5621

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

Safety Recall 00S11
Certain 2000 Windstar vehicles - Fuel Line Retention

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to $1,100 per vehicle.

PROMPTLY CORRECT

Promptly correct all affected vehicles on your dealer VIN list which you will receive in the Ford Dealer Consolidated Communicator (FDCC). Also, correct other eligible vehicles which are brought to your dealership.

DEALER-OWNER CONTACT

Immediately contact any affected owner whose name is not on the list. Give the owner a copy of the Owner Letter and schedule a service date.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer). Refer to ACESII manual for refund information.

RENTAL CARS

Rental vehicles are not approved for this program.

Safety Recall 00S11
Certain 2000 Windstar vehicles - Fuel Line Retention

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Install 2 Fuel Line Retention Clips	00S11B	0.2 Hours
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS

Parts Ordering Information

Parts will not be direct shipped for this recall. Order your parts requirement through normal order processing channels as noted below:

Stock Orders	Effective immediately	Normal order process
Interim Orders	Effective immediately	Normal order process
Emergency Orders	First 30 days after launch	Call 1-800-325-5621
Emergency Orders	31 days after launch	Normal order process

Part Number	Description	Quantity
FOAZ-9A317-B	Clip Assembly-Fuel Line Bag of 2 Clips	1

ORDER INFORMATION DOR/COR

DOR/COR number 50167 identifies parts ordered for this campaign through the Recall Hotline (1-800-325-5621) for the first 30 days.

DEALER PRICE

For latest prices, refer to:

- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121
1-800-392-3673
www.ownerconnection.com

July 2000

00S11

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in certain 2000 Windstar vehicles.

What the safety issue is…

Your vehicle may have stainless steel under body fuel supply and return line end-forms not built to drawing tolerances. This could result in lower than intended pull-off forces for the joint.

The vehicle still meets all crash requirements and there is no effect on normal vehicle operation. However, a quick connect joint with reduced pull-off force could potentially separate and leak fuel during a very severe vehicle collision.

What Ford Motor Company and your dealer will do...

Your dealer will install a retaining clip over the quick connect joint of the fuel supply and return lines of your vehicle.

Ford Motor Company will repair your vehicle free of charge (parts and labor). Owners who are affected by this recall are requested to return their vehicle to their dealer to have this repair done.

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time.

What we are asking you to do…

Call your dealer without delay. Ask for a service date and whether parts are in stock for Safety Recall 00S11.

If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week after ordering.

When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

If you've already paid for this service…

If you paid to have this service done before the date of this letter, Ford is offering a full refund. For the refund, please give your paid original receipt to your dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you've changed address or sold the vehicle…

Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns…

If you have trouble getting your vehicle repaired promptly and without charge, please contact your dealer's Service Manager. If you need further assistance, please contact the Ford Motor Company Customer Assistance Center and one of our representatives will be happy to assist you:

CALL: (800) 392-3673
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)

Monday-Friday: 8am - 11pm
Saturday: 9am - 6pm

or you may contact us through the Internet at:
www.ownerconnection.com
Our current response time to internet inquiries is three business days.

You also may send a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline 1-800-424-9393 (Washington, D. C. area residents may call 1-202-366-0123).

Quality Care service is there for you all year round.

QualityCare™ at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Again, we are sorry for the inconvenience. Thank you for your attention to this important matter.

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs