TRIM—CREASE IN HEADLINER ABOVE LEFT A-PILLAR	Article No. 03-1-4

FORD: 1999-2003 WINDSTAR

ISSUE

Some vehicles may exhibit a crease in the Headliner above the Left A-Pillar. This may be caused by the headliner to A-Pillar attachment.

ACTION

Remove the A-Pillar moulding, lower the Headliner and smooth the crease from the material. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

To remove a crease in the Headliner above the left hand side A-Pillar use the following procedure.

1. Take down the weather strip from the top of the A-Pillar to the bottom of the A-Pillar and across the top of the front driver's door.
2. Pull the A-Pillar off so that you can reach inside the top 10 inches. Do not remove it completely.
3. There is a black wire that runs up the A-Pillar and goes about 10 inches across the top of the A-Pillar before going under the main part of the Headliner. Pull the wire from the A-Pillar to the inner edge of the flange for about 10 inches from the top of the A-Pillar.
4. This will allow the Headliner to rest against the sheet metal and assume the shape of the top of the A-Pillar garnish.
5. Push on the back of the Headliner at the crease until it is smooth. The crease will still be visible before you put the A-Pillar back in place. Reshape the Headliner 4 or 5 times until the crease is relaxed.
6. Reinstall the A-Pillar and smooth the headliner again, the crease will disappear behind the A-Pillar top edge. If necessary repeat Steps 5 and 6 again.
7. When complete, reinstall the A-Pillar and the weather strip.

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
030104A	Smooth Crease From Headliner Material	0.2 Hr.

DEALER CODING

BASIC PART NO.	CONDITION CODE
1751944	34

OASIS CODES: 107000

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle.

Copyright © 2002 Ford Motor Company