Ford Motor Company

Ann O'Neill
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

April 2000

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Owner Notification Program 00B40: Certain 1999 and 2000 Model Year Explorer, Mountaineer, Ranger, Expedition, Navigator and Villager Vehicles - Multifunction Switch Replacement

REF:	Dealer Announcement dated 12/17/98, Lincoln Commitment Special Handling Procedure (Attachment IV)

OASIS: Yes

OWNER LIST: Yes

PARTS RETURN: Follow the provisions of the Warranty and Policy Manual for "Parts Retention and Return Procedures".

PROGRAM TERMS: This program has no expiration date.

AFFECTED VEHICLES

Certain 1999 and 2000 model year Explorer and Mountaineer vehicles built at the Louisville and St. Louis Assembly Plants through September 12, 1999.

Certain 1999 and 2000 model year Ranger vehicles built at the Twin Cities, Louisville and Edison Assembly Plants through September 12, 1999.

Certain 1999 and 2000 model year Expedition and Navigator vehicles built at the Michigan Truck Plant through August 17, 1999.

Certain 1999 and 2000 model year Villager vehicles built at the Ohio Assembly Plant through August 9, 1999.

REASON FOR PROGRAM

In some of the affected vehicles, the multifunction switch may develop corrosion on the front windshield wiper switch terminals affecting its signal output. The change in the signal output interferes with normal operation of the front windshield wipers. The most common condition involves the front wipers briefly turning on with the wiper switch in the "off" position. In extreme cases when this condition is ignored for some time, wiper high-speed operation may be affected.

NOTE: Owner Notification Program 00B40 is being launched concurrently with Safety Recall 00S04. ONP 00B40 involves the replacement of the multifunction switch only. Safety Recall 00S04 involves the replacement of the multifunction switch and a repair procedure to correct the potential loss of Generic Electronic Module (GEM) operation. Depending on the individual vehicle's GEM repair history and vehicle options, some Explorer/Mountaineer (A4WD) vehicles may be included in ONP 00B40 and not in

Safety Recall 00S04. PLEASE CHECK OASIS TO DETERMINE WHICH PROGRAM APPLIES TO A PARTICULAR VEHICLE.

NOTE: Some vehicle lines not included in this owner notification program may exhibit concerns where the wipers briefly turn on with the wiper switch in the "off" position. Please consult OASIS for the latest technical information pertaining to those vehicle lines.

SERVICE ACTION

Dealers will replace the multifunction switch on all affected vehicles. The replacement switch has a revised design.

NOTE 1: Explorer, Mountaineer and Ranger 4X2 vehicles without power windows are not involved in this program. Please consult OASIS for the latest technical information pertaining to those vehicles.

NOTE 2: Many vehicles have previously had the multifunction switch replaced under warranty. These vehicles are not included in this program.

NOTE 3: Owner Notification Program 00B40 supercedes TSB 99-24-03 for Explorer, Mountaineer, Ranger, Expedition, Navigator and Villager vehicles. The revised multifunction switch used in this ONP eliminates the need for Generic Electronic Module (GEM) replacement as previously described in the TSB.

REFERENCE TABLE

To help clarify the relationship between ONP 00B40, Safety Recall 00S04 and the current Technical Service Bulletin, which have some similarities to the concern, the following table is provided.

Model Year *	Vehicle	Drive Type	Option	ONP 00B40	Safety Recall 00S04	Consult OASIS for Latest TSB Information
2000	Excursion	All				X
1999-2000	Expedition/Navigator	All		X		
1999-2000	Explorer/Mountaineer	A4WD	with Load Leveling	X		
			with Memory Seat	X		
			all others without above options		X	
		AWD		X		
		4X2	with power windows	X		
			without power windows			X
1999-2000	F150-F250 Light Duty	All				X
1999-2000	Mustang	All				X
1999-2000	Ranger	4X4		X		
		4X2	with power windows	X		
			without power windows			X
1999	Taurus/Sable	All				X
1999-2000	Villager	All		X		
1999-2000	Windstar	All				X

***** See Specific Program for Build Date Ranges

NOTE: The above table is for reference only. Consult OASIS for specific vehicle eligibility.

LINCOLN COMMITMENT SPECIAL HANDLING PROCEDURE

(For Navigator Owners Only)

The Lincoln Commitment Special Handling Procedure has been activated for all Navigator owners affected by this program. Please see dealer announcement dated 12/17/98, Lincoln Commitment Special Handling Procedure (Attachment IV). The special handling procedure provides additional allowance to enable dealers to offer Lincoln owners convenient vehicle handling.

Lincoln Mercury is asking for your support and the cooperation of your sales and service teams to make this a positive experience for our Navigator customers, many of whom are new to the Lincoln family.

RENTAL CARS

Ford will pay for a loaner or rental vehicle for one (1) day except for fuel, which will be at the owner's expense. Refer to Attachment I for details.


ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Attachment IV: Lincoln Commitment Special Handling Procedure Announcement Letter
Customer Notification Letter

QUESTIONS?

Claims Information: 1-800-423-8851
Other Program Questions: 1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

Owner Notification Program 00B40

Certain 1999 and 2000 Model Year Explorer, Mountaineer, Ranger,
Expedition, Navigator and Villager Vehicles
Multifunction Switch Replacement

OASIS

You must use OASIS to determine if a vehicle is eligible for this program.

PLEASE NOTE

Correct all vehicles in stock before delivery.

PROMPTLY CORRECT

Promptly correct all affected vehicles on the enclosed list (if provided) or the VIN list in the Ford Dealership Consolidated Communicator (FDCC) and other eligible vehicles, which are brought to your dealership.

DEALER-OWNER CONTACT

Immediately contact any affected owner whose name is not on the list. Give the owner a copy of the Owner Letter and arrange for a service date.

Note: Navigator owners should receive the "Lincoln Commitment Special Handling Procedure". Before calling Navigator owners, review Attachment IV to familiarize yourself with the special handling procedure.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII Manual for claims preparation and submission information.
- To claim for the "Lincoln Commitment Special Handling", follow the instructions on page two of Attachment IV.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer). Refer to ACESII manual for refund information.

Program Code:	00B40
Misc. Expense:	REFUND
Misc. Expense:	ADMIN
Misc. Expense:	0.2 Hr.

RENTAL CARS

Ford will pay for a loaner or rental vehicle for one (1) day except for fuel, which will be at the owner's expense. The one (1) day rental should be provided only while the vehicle is at the dealership for the multifunction switch replacement. If additional rental days are needed, the days will be taken from the dealers Transportation Assistance Program (TAP) allowance. Follow Extended Service Plan (ESP) guidelines for rental dollar amounts. Enter the word "LOANER" plus the number one (1) for the number of days the vehicle was used in the Miscellaneous Expense area of the claim.

Note: Navigator owners should receive the "Lincoln Commitment Special Handling Procedure". Before calling Navigator owners, review Attachment IV to familiarize yourself with the special handling procedure.

PARTS RETENTION

Follow the provisions of the Warranty and Policy Manual for "Parts Retention and Return Procedures".

Owner Notification Program 00B40

Certain 1999 and 2000 Model Year Explorer, Mountaineer, Ranger, Expedition, Navigator and Villager Vehicles
Multifunction Switch Replacement

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Replace Multifunction Switch and Verify Connectors	00B40B	0.5 Hours
Lincoln Commitment Special Handling * (Navigator Only)	Misc. Expense Code "LCHP"	See Attachment IV

* Lincoln Commitment Special Handling does not apply to vehicles in dealer stock.

PARTS REQUIREMENTS

Parts Ordering Information

Parts will not be direct shipped for this program. Order your part requirements through normal order processing channels as noted below:

Stock Orders	Effective immediately	Normal order process
Interim Orders	Effective immediately	Normal order process
Emergency Orders	31 days after launch	Normal order process
Emergency Orders	First 30 days after launch	Call 1-800-325-5621

Vehicle	Part Number	Description	Quantity
Explorer, Mountaineer and Ranger	YL5Z-13K359-AAA	Multifunction Switch	1
Expedition and Navigator	YL1Z-13K359-AAA	Multifunction Switch	1
Villager	YF5Z-13K359-BAA	Multifunction Switch	1

DEALER PRICE

For latest prices, check or call your:

- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

Program Announcement Letter
Lincoln Commitment Special Handling

Ford Customer Service Division

Ford Motor Company
P.O. Box 1904
Dearborn, Michigan 48121

December 17, 1998

To: All Lincoln Mercury and Ford Dealers

cc: Parts Managers
Service Managers

Subject: Announcing Lincoln Commitment Special Customer Handling Procedure for Certain Recalls and Owner Notification Programs

As part of our ongoing commitment to Lincoln customers, we are pleased to announce the Lincoln Commitment Special Customer Handling Procedure to provide additional dealer compensation for certain Recalls and Owner Notification Programs (ONP's) that affect Lincoln brand vehicles.

This additional compensation is being provided to allow dealers to provide personalized service designed to make the recall repair a positive experience for the Lincoln customer, many of whom are new to the Lincoln family.

Each Recall/ONP Bulletin affecting Lincoln vehicles will indicate whether the Lincoln Commitment Special Customer Handling Procedure is authorized; please note that not every Recall/ONP will qualify for this procedure and that the procedure will not be communicated to customers as a normal benefit of the Lincoln Commitment Program. Special handling and claiming instructions are included on the attached page. This program will apply only to Lincoln vehicles, which have been delivered to customers.

We ask you to make maximum usage of these special enhancements to the Lincoln Commitment Program when applicable. Thank you in advance for your support of this program and our commitment to surprise and delight our Lincoln customers.

/O.S.B./
Mark Hutchins
President
Lincoln Mercury

/O.S.B./
M. D. Jordan
Executive Director
Ford Customer Service Division
North America

Lincoln Commitment Special Handling (Continued)

If Dealer Picks up and Returns Vehicle for Customer:

Special Service	Dealer Compensation	Claim Procedure
• Pick up the customer's vehicle (at a location of their preference such as home or place of business) and return after repair* • Drop off comparable loaner vehicle • Refill fuel tank • Wash and vacuum vehicle • Return vehicle to customer after repair is completed	Up to 2 hours additional labor (converted to a dollar amount) plus actual cost of fuel and wash/vacuum **Note:** Labor time to fill tank and wash/vacuum has been included in 2 hour allowance Labor subject to time recording procedures as outlined in Warranty & Policy Manual	Submit total dollar value (labor+fuel+wash/vacuum) using Misc. Expense Code "LCHP" EXAMPLE (using example labor rate of $58/hour and fuel cost of $1.05/gallon): 1.2 hrs. labor* = $69.60 9.0 gals fuel = 9.45 Wash/vacuum = 3.50 Total Submitted = $82.55 *travel time plus fueling and washing labor
Provide comparable loaner vehicle to customer when vehicle is picked up	Actual cost up to a maximum of $35 per day for a Lincoln loaner or up to $18 per day for a Mercury or Ford loaner (This does not count against TAP allocation)	Submit up to 3 days maximum using "LOANER" (if additional days are required, call 1-800-325-5621 for authorization)
Perform Recall/ONP repair at dealership	Inspection/repair labor allowance as specified in Recall/ONP Bulletin	See applicable Recall/ONP Bulletin

*Or repair on-site if appropriate; if on-site repair is performed, rental charges do not apply.

If Customer Brings Vehicle to Dealer:

Special Service	Dealer Compensation	Claim Procedure
Perform Recall/ONP repair at dealership	Inspection/repair labor allowance as specified in Recall/ONP Bulletin	See applicable Recall/ONP Bulletin
Provide comparable loaner vehicle to customer	Actual cost up to a maximum of $35 per day for a Lincoln loaner or up to $18 per day for a Mercury or Ford loaner (This does not count against TAP allocation)	Submit up to 3 days maximum using "LOANER" (if additional days are required, call 1-800-325-5621 for authorization)
Refill fuel tank and wash/ vacuum vehicle	Up to 0.5 hour additional labor (converted to a dollar amount) plus	Submit total dollar value (labor+fuel+wash/vacuum)

	actual cost of fuel and wash/vacuum	using Misc. Expense Code “LCHP”

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121
1-800-392-3673
www.ownerconnection.com

Ford Motor Company

May 2000

00B40

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

Ford Motor Company is providing a no-charge service, Program Number 00B40, to owners of certain 1999 and 2000 model year Explorer, Mountaineer, Ranger, Expedition, Navigator and Villager vehicles.

Reason For This Program

In some of the affected vehicles, the front windshield wiper switch may develop internal corrosion affecting its operation and signal output. The change in the signal output interferes with normal operation of the front windshield wipers. The most common condition involves the front wipers briefly turning on with the wiper switch in the "off" position. In extreme cases when this condition is ignored for some time, wiper high-speed operation may be affected.

What *Ford Motor Company* and your dealer will do…

At no cost to you, your dealer will replace the front windshield wiper switch with a revised design to correct the concern.

What we are asking you to do…

Call your dealer without delay. Ask for a service date and whether parts are in stock for Owner Notification Program 00B40.

If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week after the order is placed.

How long will it take….

The time needed for this repair is less than one-half day. However, due to service scheduling requirements, your dealer may need your vehicle for a longer period of time.

When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

If you've already paid for this service…

If you paid to have this service done before the date of this letter, Ford is offering a full refund. For the refund, please give your paid original receipt to your Ford or Lincoln Mercury dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you need a loaner vehicle…

Your dealer is authorized to provide a free loaner vehicle (except for fuel) for the one (1) day your vehicle is at the dealership for the wiper switch replacement.

If you've changed address or sold the vehicle…

Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns…

If you have trouble getting your vehicle repaired promptly and without charge, please contact the Ford Motor Company North American Customer Assistance Center and one of our representatives will be happy to assist you:

CALL: (800) 392-3673
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)

Monday-Friday: 8am - 11pm
Saturday: 9am - 6pm

Or contact us through the web at: www.ownerconnection.com

Current response time is three business days.

Quality Care service is there for you all year round.

QualityCare™ at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our Ford and Lincoln Mercury dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Again, we are sorry for the inconvenience. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs