• **LAMP—COURTESY, GLOVE COMPARTMENT, UNDERHOOD, RUNNING BOARD LAMPS INOPERATIVE IN MORNING OR AFTER VEHICLE IS LEFT UNATTENDED FOR 45 MINUTES** • **POWER WINDOWS—INOPERATIVE IN MORNING OR AFTER VEHICLE IS LEFT UNATTENDED FOR 45 MINUTES** • **RADIO—INOPERATIVE IN MORNING OR AFTER VEHICLE IS LEFT UNATTENDED FOR 45 MINUTES** • **REAR WIPER—INOPERATIVE IN MORNING OR AFTER VEHICLE IS LEFT UNATTENDED FOR 45 MINUTES**	**Article No. 00-19-2**

FORD: 1999-2000 EXPEDITION, F-150, F-250 LD

LINCOLN: 1999-2000 NAVIGATOR

This article is being republished in its entirety to update the part number.

ISSUE

A temporary loss of functions controlled by the battery saver relay may occur on some vehicles. These functions may be inoperative for a short period of time after the vehicle has sat unattended for at least 45 minutes. These functions are limited to courtesy and interior/demand lamps, glove compartment, underhood lamps and power windows. Running board lights, moonroof and the rear wiper may be affected on Expedition and Navigator. The radio may also be inoperative during this time on Navigator only. The loss of these features is temporary and can last from a few seconds up to 10-15 minutes.

ACTION

Replace the Battery Saver Relay (YL3Z-14N089-AA). Refer to the appropriate Electrical and Vacuum Troubleshooting Manual (EVTM) for location of this relay.

NOTE

PERMANENT LOSS OF ANY OF THESE FUNCTIONS SHOULD NOT BE ADDRESSED WITH THIS TSB. FUNCTIONS OTHER THAN THOSE EXPLICITLY MENTIONED ABOVE THAT ARE REPORTED TO BE INOPERATIVE SHOULD NOT BE ADDRESSED WITH THIS TSB.

PART NUMBER	PART NAME
YL3Z-14N089-AA	Battery Saver Relay

OTHER APPLICABLE ARTICLES: NONE
SUPERSEDES: 00-8-7
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
001902A	Replace Battery Saver Relay	0.2 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
14489	42

OASIS CODES: 102000, 201000, 201100, 201200, 202000, 203000, 205000, 207000