BRAKES—REAR DRUM—GRABBING DURING FIRST FEW BRAKE APPLICATIONS WHILE BRAKES ARE COLD	Article No. 01-19-2

FORD: 1997-2000 F-150

This article is being republished in its entirety to update the Model Year coverage.

ISSUE

A grabbing condition from the rear brakes during the first few brake applications after extended humidity exposure may occur on some vehicles. This may be caused by a rear brake lining that is sensitive to humidity exposure.

ACTION

Replace rear brake linings with revised Rear Shoe Brake Kit (F85Z-2200-AA). Refer to the appropriate model year F-150 Workshop Manual, Section 206-02 for service details.

PART NUMBER	PART NAME
F85Z-2200-AA	Rear Shoe Brake Kit

OTHER APPLICABLE ARTICLES: NONE
SUPERSEDES: 99-10-7
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
011902A	Replace Rear Brake Shoes	1.2 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
2200	49

OASIS CODES: 301000, 702200

Copyright © 2001 Ford Motor Company