- **DRIVEABILITY—IDLE—HIGH IDLE SPEEDS—THROTTLE STICKS AFTER STEADY STATE DRIVING IN EXTREME COLD AMBIENT TEMPERATURES—VEHICLES BUILT THROUGH 12/31/01 EQUIPPED WITH 4.6L ENGINE**
- **4.6L—IDLE—HIGH IDLE SPEEDS—THROTTLE STICKS AFTER STEADY STATE DRIVING IN EXTREME COLD AMBIENT TEMPERATURES—VEHICLES BUILT THROUGH 12/31/01 EQUIPPED WITH 4.6L ENGINE**

Article No. 02-19-3

FORD: 1997-1999 F-250 LD
1997-2002 EXPEDITION, F-150

ISSUE

In rare instances, throttle sticking may occur on a few vehicles in very cold ambient temperatures after operating at steady speed or extended idle for a period of time. This may be due to ice build-up from moisture in the PCV gas on the throttle plate or throttle body.

ACTION

Verify the condition is not caused by throttle body sludging, throttle cable binding, or interference between an improperly positioned floor mat and accelerator pedal. If no other conditions are identified, check for evidence of PCV system backflow. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

Inspect the inside of the clean air tube at the PCV closure hose connection for presence of moisture, oil, or oily stains. If evidence of PCV system backflow is found, replace the PCV system with the PCV Service Kit 1L3Z-6A603-AA. Refer to the Instruction Sheet within the PCV Service Kit for Service Procedure.

PART NUMBER	PART NAME
1L3Z-6A603-AA	PCV Service Kit

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage And Emissions Warranty Coverage

OPERATION	DESCRIPTION	TIME
021903A	Replace PCV System with PCV Service Kit: 1997-2002 F-150, Expedition 1997-1999 F-250 LD	1.5 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
6C324	42

OASIS CODES: 401000, 402000, 404000, 499000, 617400, 619400

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle.

Copyright © 2002 Ford Motor Company