• THUMP/CLUNK HEARD ON LIGHT ACCELERATION FROM A STOP OR WHEN BRAKING AND COMING TO A STOP

• DRIVESHAFT—THUMP/CLUNK HEARD ON LIGHT ACCELERATION FROM A STOP OR WHEN BRAKING AND COMING TO A STOP

Article No. 02-19-2

FORD: 1998-2002 RANGER

Article **01-11-11** is being republished in its entirety to update the model year coverage and to update the parts involved.

ISSUE

Some 4X4 Super Cab vehicles, built before 5/10/02 (excluding FX4) may exhibit a low frequency thump type noise/vibration on light acceleration from a stop, and/or when coming to a stop with light to moderate braking. This may be caused by axle wind up during acceleration or deceleration and creating a stick/slip condition at the rear driveshaft slip-joint splines causing the thump/clunk sensation.

ACTION

Replace 3.5 inch steel driveshaft with 4.0 inch aluminum rear driveshaft. This requires installation of a revised fuel tank skid plate for vehicles built before 1/15/2001 equipped with the 4X4 Off-Road package. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

1. Reference yellow balance mark on existing steel driveshaft. Using chalk, paint-pen or equivalent, index a mark on the rear axle flange in-line with yellow mark on driveshaft. This will enable the new driveshaft to be reinstalled in an original balanced state.
2. Remove existing steel driveshaft from vehicle.
3. Using the previous reference mark on the axle, align the applicable revised aluminum driveshaft yellow mark to the axle flange mark. This will assure correct orientation of the new service driveshaft.

CAUTION

IF NEW BOLTS TO RETAIN THE DRIVESHAFT TO THE AXLE ARE NOT AVAILABLE, COAT THE THREADS OF THE ORIGINAL BOLTS WITH THREADLOCK AND SEALER EOAZ-19554-AA OR EQUIVALENT MEETING FORD SPECIFICATION WSK-M2G351-A5.

4. Install new service driveshaft and torque all eight (8) fasteners to 65-87 Lb-ft (88-119 N•m).
5. Remove fuel tank skid plate for vehicles built before 1/15/2001 equipped with the 4X4 Off-Road package.
6. Replace with new service Skid Plate (1L5Z-9A147-AA).
7. Torque fuel tank skid plate fasteners to 25-34 Lb-ft (34-46 N•m).
8. Verify condition has been corrected by accelerating from a stop, and/or with light to moderate braking when coming to a stop.

PART NUMBER	PART NAME
1L5Z-4602-JM	Driveshaft (1998-2000 Ranger)
1L5Z-4602-LB	Driveshaft (2001-2002 Ranger)
1L5Z-9A147-AA	Fuel Tank Skid Plate
EOAZ-19554-AA	Threadlock And Sealer

OTHER APPLICABLE ARTICLES: NONE
SUPERSEDES: 01-11-11
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
021902A	Replace Driveshaft (Vehicles Without Fuel Tank Skid Plate)	0.7 Hr.
021902B	Replace Driveshaft And Fuel Tank Skid Plate	0.8 Hr.

Copyright © 2002 Ford Motor Company

DEALER CODING

BASIC PART NO.	CONDITION CODE
4602	42

OASIS CODES: 597997, 702000, 702200, 702300, 703000, 703200, 703400

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle.