• **ELECTRICAL—DIAGNOSTIC TROUBLE CODES (DTC) B1876, B1880, B1915 AND/OR B1920 AIRBAG ELECTRONIC CRASH SENSOR (ECS) MODULE—VEHICLES EQUIPPED WITH AFTERMARKET HIGH-CURRENT DEVICES** • **ELECTRICAL—VEHICLES EQUIPPED WITH AFTERMARKET HIGH-CURRENT DEVICES—DIAGNOSTIC TROUBLE CODES (DTC) B1876, B1880, B1915 AND/OR B1920 AIRBAG ELECTRONIC CRASH SENSOR (ECS) MODULE**	**Article No. 01-23-4**

FORD: 1997-2002 E SERIES

ISSUE

Some vehicles with aftermarket high-current devices (such as motors for wheel chair lifts) operating at 75 amps or higher may cause electrical transients (voltage spikes) leading to damage of the Airbag Electronic Crash Sensor (ECS) Module. If this occurs, the airbag lamp will illuminate indicating that there is a fault in the airbag system and Diagnostic Trouble Codes (DTC) B1876, B1880, B1915 and/or B1920 will be present.

ACTION

Follow normal diagnostics located in section 501-20B of the E-Series Workshop Manual. If the pinpoint tests lead to a replacement of the ECS module and the vehicle contains high-current aftermarket equipment, installation of the ECS Module Circuit Protection Improvement Kit is recommended to prevent recurring damage from the aftermarket equipment to the new ECS module.

For this condition, installation of the ECS Module Circuit Protection Improvement Kit will only protect a non-damaged module. If the module has been damaged, (DTCs B1876, B1880, B1915 and/or B1920 are present in the module and no other issues found in the system), the ECS module will have to be replaced.

SERVICE PROCEDURE

NOTE

READ AND FOLLOW ALL WARNINGS LOCATED IN SECTION 501-20B OF THE E-SERIES WORKSHOP MANUAL BEFORE PERFORMING ANY PROCEDURE OR TESTS ON THE RESTRAINTS SYSTEM.

If Airbag Electronic Crash Sensor (ECS) Module contains DTCs B1876, B1880, B1915 and/or B1920, and the Pinpoint tests lead to module replacement, check for any type of high-current aftermarket equipment such as wheel chair lifts.

If all conditions are met, it is recommended that the ECS Module Circuit Protection Improvement Kit (Kit Service Number: 2C2Z-14S411-AA) be ordered and installed. This kit contains a detailed installation procedure.

Costs of this additional protection of the ECS from the aftermarket equipment are not covered in warranty and are the responsibility of the modifier or customer.

PART NUMBER	PART NAME
2C2Z-14S411-AA	Electronic Crash Sensor (ECS) Module Circuit Protection Improvement Kit

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 104000, 206000

Copyright © 2001 Ford Motor Company