• **LOSS OF POWER—WHILE DRIVING IN RAIN—F-53 STRIPPED CHASSIS VEHICLES WITH 6.8L ENGINE BUILT THROUGH 2/5/2001** • **STUMBLE—WHILE DRIVING IN RAIN—F-53 STRIPPED CHASSIS VEHICLES WITH 6.8L ENGINE BUILT THROUGH 2/5/2001**	**Article No. 02-9-9**

FORD: 1999-2002 SUPER DUTY F-53 STRIPPED CHAS.

This article is being republished in its entirety to update the model year coverage.

ISSUE

Some vehicles may ingest an excessive amount of water into the air filter while driving in the rain. Excessive water can cause loss of power and/or engine stumble. This may be caused by the air cleaner shield.

ACTION

Replace current air cleaner shield with new gasket and shield kit. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

NOTE

REFER TO THE INSTRUCTION SHEET INCLUDED IN THE SERVICE KIT FOR THE ILLUSTRATIONS MENTIONED IN THIS ARTICLE.

NOTE

THE INDIVIDUAL PARTS LISTED IN THE FOLLOWING PROCEDURE ARE PART OF THE AIR CLEANER SHIELD SERVICE KIT (YC3Z-9K635-AA).

1. Remove and discard existing air cleaner shield; retain fasteners.
2. Remove air filter and lower air cleaner housing. Inspect filter for damage and replace as necessary.
3. Insert two (2) plug buttons 377977-S into holes in the housing. (Refer to Instruction Sheet).
4. Insert lower housing through new air cleaner shield gasket YC3Z-9654-AA. (Refer to Instruction Sheet).
5. Reinstall lower housing with gasket and air filter.
6. Install new air cleaner shield YC3Z-9D619-AA using outboard fastener first. Wrap shield around gasket and install inboard fastener. (Refer to Instruction Sheet).

PART NUMBER	PART NAME
YC3Z-9K635-AA	Air Cleaner Shield Service Kit

OTHER APPLICABLE ARTICLES: NONE
SUPERSEDES: 00-20-2
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
020909A	Install Air Cleaner Shield	0.3 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
9C662	49

OASIS CODES: 607000, 607400, 608000, 608400, 611000, 611500, 614000, 614500, 614600

Copyright © 2002 Ford Motor Company