Service Recall Bulletin

March 2000

TO: Ford and Lincoln Mercury Dealers

SUBJECT: **DEMONSTRATION/DELIVERY HOLD:** Emission Recall 00E09**:** Certain 2000 Model Year Focus Vehicles with 2.0L Zetec Engines - Injector Pressure Sensor Replacement

AFFECTED VEHICLES

All 2000 model year Focus vehicles with 2.0L Zetec engines built at the Wayne and Hermosillo Assembly Plants through January 26, 2000.

REASON FOR RECALL

In some of the affected vehicles, the Injector Pressure Sensor (IPS), located on the end of the fuel rail, may become contaminated with water during engine shipping to the assembly plant. This water contamination in the IPS can freeze in cold ambient temperatures and cause the IPS membrane to crack or burst. This damage to the IPS could cause powertrain and emission control concerns such as:

- illumination of the Malfunction Indicator Lamp (MIL)
- engine no-start
- internal engine damage due to hydro-locking

SERVICE PROCEDURE

Before demonstrating or delivering any of the affected vehicles in dealer stock, the dealer must replace the IPS. Additionally, the dealer will perform this recall procedure on all affected vehicles that have been delivered to customers.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information

QUESTIONS?

Claims Information: 1-800-423-8851
Other Recall Questions: 1-800-325-5621

Sincerely,

Ann O'Neill
Director

DEMONSTRATION/DELIVERY HOLD: Emission Recall 00E09
Certain 2000 Model Year Focus Vehicles with 2.0L Zetec Engines
Injector Pressure Sensor Replacement

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

PLEASE NOTE

Correct all vehicles in stock before delivery.

PROMPTLY CORRECT

Promptly correct all affected vehicles on the enclosed VIN list (if provided) or the VIN list in the Ford Dealer Consolidated Communicator (FDCC) and other eligible vehicles, which are brought to your dealership.

DEALER-OWNER CONTACT

- Immediately contact any affected owner whose name is not on the list.
- Give owner a copy of the Owner Letter.

REGIONAL CONTACT

Advise regional office if:

- an owner cannot be contacted.
- an owner does not make a service date.

CLAIMS SUBMISSION

Enter claims using DWE. See ACESII Manual.

PARTS RETENTION

Follow the provisions of the Warranty and Policy Manual for "Parts Retention and Return Procedures".

RENTAL CARS

Ford will pay for a loaner or rental vehicle except for fuel, which will be at the owner's expense. Rentals should be provided only while the vehicle is at the dealership for the IPS replacement. Follow Extended Service Plan (ESP) guidelines for rental dollar amounts. Enter the word "LOANER" plus the number of days the vehicle was used in the Miscellaneous Expense area of the recall claim.

DEMONSTRATION/DELIVERY HOLD: Emission Recall 00E09
Certain 2000 Model Year Focus Vehicles with 2.0L Zetec Engines
Injector Pressure Sensor Replacement

LABOR ALLOWANCES

Description	Labor Operation	Time
Replace Injector Pressure Sensor (IPS)	00E09B	0.4 Hrs.
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hrs.

PARTS REQUIREMENTS

Part Ordering Information

Parts to repair 15% of involved units will be direct shipped (seed stock) to dealers (via interim and stock orders) by March 3, 2000. An additional 15% will be direct shipped (via stock orders) by March 10, 2000. Please refrain from ordering any parts until after you have received your seed stock. To discontinue your seed stock allocation, please call 1-800-325-5621. Ordering procedures are as follows:

All Order Types	BEFORE 3/13/00	Call 1-800-325-5621
Emergency Orders	From 3/13/00 through 5/5/00	Call 1-800-325-5621
Interim/Stock Orders	After 3/13/00	Normal order process

Please Note: Most dealers will have 20 or less involved units.

Part Number	Quantity	Description
XS4Z-9F972-DA	1	Injector Pressure Sensor
FPS-8262	1	Authorized Modifications Label

DEALER PRICE

For latest prices, check:

- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

Ann O'Neill
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

March 2000

Emissions Recall - 00E09 -- Owners in Federal Locations

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

Ford Motor Company values you as a customer and we also value our commitment to vehicle quality and the environment. We are therefore voluntarily recalling certain 2000 model year Focus vehicles with 2.0L Zetec engines.

REASON FOR RECALL

In some of the affected vehicles, the Injector Pressure Sensor (IPS), located on the end of the fuel rail, may contain water that can freeze in cold outside temperatures and cause the IPS membrane to crack or burst. This damage to the IPS could cause powertrain and emission control concerns such as:

- illumination of the Malfunction Indicator Lamp (MIL)
- the engine will not start
- internal engine damage due to hydro-locking

WHAT THE DEALER WILL DO

At no cost to you, your dealer will replace the Injector Pressure Sensor according to the instructions provided by Ford.

This service should have no effect on your Focus except to prevent damage to the IPS and engine.

If you do not have this service done:

- Your emissions warranty may be reduced.
- Your vehicle may not pass emissions or smog tests that may be required in your area.
- You may experience engine damage or failure.

HOW LONG WILL IT TAKE?

The time needed to repair your Focus is about one-half day. However, due to service scheduling requirements, your dealer may need your vehicle longer.

CALL YOUR DEALER

Call your dealer without delay. Ask for a service date for Emissions Recall 00E09 and if parts are in stock.

If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week of placing the order.

When you bring your Focus in, show your dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

RENTAL VEHICLES

To make this repair experience as convenient as possible, your dealer is authorized to provide a free "Loaner" vehicle (except for fuel) while your vehicle is at the dealer for IPS replacement.

CHANGED ADDRESS OR SOLD THE FOCUS?

If you have changed your address or sold your Focus, please fill out the enclosed prepaid postcard and mail it to us.

If the repair offered by this recall is not made promptly and without charge, talk to the dealer service manager. You may also contact the Ford Customer Assistance Center by calling toll-free 1-800-392-3673, (1-800-392-FORD), or by writing to Ford Customer Assistance Center, P. O. Box 6248, Dearborn, Michigan 48121.

Please have your Focus serviced promptly to maintain full emission warranty coverage.

We regret the inconvenience this recall may cause you. We are taking this action to ensure your continued satisfaction with your Ford-built Focus.

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

Ann O'Neill
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

March 2000

Emissions Recall - 00E09 -- Owners of California Certified Vehicles, Including Massachusetts Owners

Mr. John Sample
123 Main Street
Anywhere, California / Massachusetts 12345

Your Vehicle Identification Number: 12345678901234567

Ford Motor Company values you as a customer and we also value our commitment to vehicle quality and the environment. We are therefore voluntarily recalling certain 2000 model year Focus vehicles with 2.0L Zetec engines.

REASON FOR RECALL

In some of the affected vehicles, the Injector Pressure Sensor (IPS), located on the end of the fuel rail, may contain water that can freeze in cold outside temperatures and cause the IPS membrane to crack or burst. This damage to the IPS could cause powertrain and emission control concerns such as:

- illumination of the Malfunction Indicator Lamp (MIL)
- the engine will not start
- internal engine damage due to hydro-locking

WHAT THE DEALER WILL DO

At no cost to you, your dealer will replace the Injector Pressure Sensor according to the instructions provided by Ford.

This service should have no effect on your Focus except to prevent damage to the IPS and engine.

If you do not have this service done:

- Your emissions warranty may be reduced.
- Your Focus may not pass emissions or smog tests that may be required in your area.
- Your state Department of Motor Vehicles may not renew your vehicle's registration.
- You may experience engine damage or failure.

HOW LONG WILL IT TAKE?

The time needed to repair your Focus is about one-half day. However, due to service scheduling requirements, your dealer may need your vehicle longer.

CALL YOUR DEALER

Call your dealer without delay. Ask for a service date for Emissions Recall 00E09 and if parts are in stock.

If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week of placing the order.

When you bring your Focus in, show your dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

RENTAL VEHICLES

To make this repair experience as convenient as possible, your dealer is authorized to provide a free "Loaner" vehicle (except for fuel) while your vehicle is at the dealer for IPS replacement.

CHANGED ADDRESS OR SOLD THE FOCUS?

If you have changed your address or sold your Focus, please fill out the enclosed prepaid postcard and mail it to us.

If the repair offered by this recall is not made promptly and without charge, talk to the dealer service manager. You may also contact the Ford Customer Assistance Center by calling toll-free 1-800-392-3673, (1-800-392-FORD), or by writing to Ford Customer Assistance Center, P. O. Box 6248, Dearborn, Michigan 48121.

OWNERS OF AFFECTED VEHICLES REGISTERED IN CALIFORNIA OR MASSACHUSETTS

The State of California and the Commonwealth of Massachusetts requires the completion of emissions recall repairs prior to vehicle registration renewal. Your Focus is subject to these requirements.

When this recall repair is completed by your dealer, you will receive a Vehicle Emissions Recall - Proof of Correction Certificate. This certificate says that this emission recall has been performed on your Focus.

Please make sure that you get a certificate from the dealer and that you have it when you renew the registration for your Focus.

It is also important for you to know that the certificate should be returned to the Department of Motor Vehicles (DMV) only if it is requested by the DMV. Otherwise, the certificate is to be held by you for your records.

In order to ensure your full protection under emissions warranty provisions and to avoid any inconvenience when renewing your registration, it is recommended that you have your vehicle serviced as soon as possible. Failure to do so could be determined as lack of proper maintenance of your vehicle.

We regret the inconvenience this recall may cause you. We are taking this action to ensure your continued satisfaction with your Ford-built Focus.

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs