• BRAKES—INCORRECT ROTOR THICKNESS STAMPED ON ROTOR—F-150 4X2 ONLY • BRAKES—INCORRECT WORKSHOP MANUAL ROTOR DISCARD THICKNESS SPECIFICATION	Article No. 99-25-6

FORD: 1997-2000 EXPEDITION, F-150, F-250 LD

LINCOLN: 1998-2000 NAVIGATOR

ISSUE

The 1997-2000 Workshop Manuals do not provide the correct and complete specification for rotor discard thickness. Additionally, some 4X2 F-150 rotors may have an incorrect rotor discard thickness stamped on them.

ACTION

Refer to the following Front and Rear Disc Rotor Discard Specification Charts for correct rotor discard specification.

FRONT DISC ROTOR DISCARD SPECIFICATION	
Vehicle Application	**Minimum Rotor Thickness**
F-150, 1997-2000, 4X4	24.5mm
F-150, 1997-2000, 4X2	24.5mm*
F-150/F-250 LD, 1998-2000, 4X4	27.7mm
F-150/F-250 LD, 1998-2000, 4X2	27.7mm
Expedition/Navigator, 1997-2000, 4X4	27.7mm
Expedition/Navigator, 1997-2000, 4X2	27.7mm

REAR DISC ROTOR DISCARD SPECIFICATION	
Vehicle Application	**Minimum Rotor Thickness**
F-150/F-250 LD, 1997-2000, 4X4	12.0mm
F-150/F-250 LD, 1997-2000, 4X2	12.0mm
Expedition/Navigator, 1997-2000, 4X4	12.0mm

*** SOME 4X2 F-150 ROTORS SHOW "24.7mm" PRINTED ON THE ROTOR BACK SIDE. THIS IS AN ERROR, THESE CAN BE CUT TO 24.5mm DISCARD THICKNESS.**

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 301000, 390000