• **ELECTRICAL—TRANSMISSION CONTROL INDICATOR LAMP (TCIL) ILLUMINATED—DIAGNOSTIC TROUBLE CODES (DTC) P0713 OR VARIOUS OTHER TRANSMISSION DTCS—VEHICLES BUILT 11/13/2000 THROUGH 3/8/2001** • **TRANSMISSION—5R55W—TRANSMISSION CONTROL INDICATOR LAMP (TCIL) ILLUMINATED—DIAGNOSTIC TROUBLE CODES (DTC) P0713 OR VARIOUS OTHER TRANSMISSION DTCS—VEHICLES BUILT 11/13/2000 THROUGH 3/8/2001**	**Article No. 01-10-7**

FORD: 2002 EXPLORER

MERCURY: 2002 MOUNTAINEER

ISSUE

Some 2002 Explorer/Mountaineer vehicles built 11/13/2000 through 3/8/2001 equipped with a 5R55W transmission may exhibit a Transmission Control Indicator Lamp (TCIL) flashing with various Diagnostic Trouble Codes (DTCs) in self test. DTC P0713 is the code that is most prevalently retrieved. This may be caused by water intrusion into the transmission solenoid body connector.

ACTION

If a vehicle comes in for this condition, check the transmission solenoid body connector (C199) for signs of water intrusion. If present, replace the Transmission Wire Harness with part number 1L2Z-7C078-AB. A new harness has been released to prevent this condition. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

TRANSMISSION HARNESS REPLACEMENT

1. Disconnect battery.
2. Remove transmission connector from Power Train Electronic Controller (PTEC), center pocket.
3. Remove transmission harness (7C078) from retainers along dash panel.
4. Ensure the transmission wiring harness is loosened at the rear of the engine.
5. Attach a length of wire or string to the PTEC connector to assist in pulling/routing of the new transmission wiring harness back up from below the vehicle in repair Steps 14 and 16.
6. Raise vehicle on hoist.
7. Pull the transmission harness down from above leaving the wire/string in place for repair Steps 14 and 16.
8. Remove the old transmission harness from the rest of the transmission.
9. Carefully clean around the solenoid body connector prior to disconnecting to prevent contamination from getting into the connector.
10. Blow out the solenoid body connector to ensure it is dry.
11. Lubricate the O-rings in the solenoid body connector with dielectric grease to ease assembly.
12. Torque the solenoid body connector screw to 5 N•m (44 lb-in). DO NOT OVERTIGHTEN.
13. Reroute the new harness onto the transmission.
14. Using the previously routed wire/string, attach to the PTEC connector.
15. Lower the vehicle off the hoist.
16. Pull the transmission harness back up from below.

Copyright © 2001 Ford Motor Company

17. Reroute the wiring along the dash panel and attach in the retainers.
18. Reconnect transmission connector to PTEC, center pocket. Torque the PTEC connector screw at 6 N•m (53 lb-in).
19. Raise the vehicle on the hoist to install one (1) pushpin for the harness at the back of the engine that is not accessible at Step 17.
20. Lower the vehicle off the hoist.
21. Reconnect battery.
22. Verify repair.

NOTE

AN ADAPTIVE LEARNING STRATEGY IN THE PCM CONTROLS THE SHIFT FEEL AND TIMING ON THE TRANSMISSION. THIS FEATURE IS DESIGNED TO INCREASE DURABILITY AND PROVIDE CONSISTENT SHIFT FEEL OVER THE LIFE OF THE VEHICLE. AS A RESULT OF THE BATTERY BEING DISCONNECTED, THE TRANSMISSION MAY HAVE FIRM AND/OR SOFT SHIFTS. THIS OPERATION IS CONSIDERED NORMAL AND WILL NOT AFFECT FUNCTION OR DURABILITY OF THE TRANSMISSION. ONCE THE VEHICLE IS AT OPERATING TEMPERATURE IT MAY TAKE SEVERAL SHIFTS AT THE SAME OPERATING CONDITION FOR THE TRANSMISSION TO PROPERLY ADAPT. OVER TIME, THE ADAPTIVE LEARNING PROCESS WILL FULLY UPDATE TRANSMISSION OPERATION. THE MORE VARIED THE DRIVING HABITS, SPEED AND TORQUE, THE LONGER IT MAY TAKE TO ADAPT BUT THE MORE COMPLETE THE PROCESS WILL BE. ADDITIONALLY, THE RESETTING OF KEEP ALIVE MEMORY (KAM) SUCH AS PCM DISCONNECT, BATTERY DISCONNECT, OR INSTALLATION OF A NEW BATTERY, THE STRATEGY MUST RELEARN.

PART NUMBER	PART NAME
1L2Z-7C078-AB	Transmission Wire Harness

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
011007A	Replace Transmission Wire Harness	1.1 Hr.

DEALER CODING

BASIC PART NO.	CONDITION CODE
7C078	X2

OASIS CODES: 206000, 501000, 502000, 503000, 504000, 698298