TRANSAXLE—4F27E—"GREEN" PRIOR TO REPAIR TAG	Article No. 99-16-6

FORD: 2000 FOCUS

ISSUE

The Focus has a new automatic transaxle called the 4F27E. This transaxle will have a green "Prior to Repair" tag on the transaxle pan. The green tag refers to this TSB and provides a toll-free phone number to be used by all U.S. and Canadian dealers for further service direction (not applicable outside the U.S. or Canada).

ACTION

Prior to September 1, 2000, do not disassemble or attempt internal repairs without contacting the toll-free number. The dealer may be authorized to make repairs or receive a replacement transaxle. Perform the following diagnostic steps and record your findings before contacting Ford Motor Company at the number listed on the green tag (1-800-349-2946). After September 1, 2000, follow the appropriate Workshop Manual for diagnostic or repair information.

SERVICE PROCEDURE

1. Check and record transaxle fluid level. If low, fill with MERCON®V Automatic Transmission Fluid (XT-5-QM) to the proper level and check for leakage. If a leak is the only concern, call the toll-free number prior to repair.
2. Check the harness connectors for proper installation at the Transaxle Range (TR) sensor, Turbine Shaft Speed (TSS) sensor, Output Shaft Speed (OSS) sensor, and the transaxle connector.
3. Perform EEC system Quick Tests and record all codes.
4. If no fault codes are present, go to Step 5. If fault codes are present, perform the required Pinpoint Tests for any fault codes received and repair all non-transaxle codes. Then, verify that the transaxle symptom still exists.
5. If there are still concerns, check external shift linkages and "non-factory" add-on items that could affect transaxle operation.
6. If the transaxle requires service, call Ford Motor Company at the toll-free number (1-800-349-2946 U.S. and Canadian dealers only). Do not disassemble the transaxle prior to calling this number. All diagnostic information must be recorded (fluid level, diagnostic codes, transaxle concern, VIN number, transaxle ID number, and results of a road test) before calling Ford Motor Company.

PART NUMBER	PART NAME
XT-5-QM	MERCON®V Automatic Transmission Fluid (ATF)

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
991606A	Perform Transaxle Diagnostics	1.3 Hrs.
991606B	If PC/ED Diagnostics Are Required, Use "A" Time Per The Warranty And Policy Manual	

Article No. 99-16-6 Cont'd.

DEALER CODING

BASIC PART NO.	CONDITION CODE
7000	42

OASIS CODES: 504000

Figure 1 - Article 99-16-6